

SATQUERY AI — EARTH OBSERVATION REPORT


Remote Sensing Inspection & Telemetry

Report ID:	7a9dcd437d63475a	Generated:	2026-09-07T17:47:32
Confidence:	High (0.87)	Imagery Count:	2 scene(s)
Visual Query:	Detect changes between T1 baseline and T2 monitoring scene	Evidence Type:	change_overlay

Executive Summary & Findings

{ "summary": "A significant transformation has occurred within the primary port infrastructure, encompassing approximately 7.6% of the total scene. This alteration, identified as a single major cluster, indicates substantial changes in surface characteristics and likely operational layout within the container terminal and adjacent port facilities.", "detailed_analysis": { "scene_overview": "The geographic footprint captures a bustling coastal

Visual Evidence Grounding



Multi-Angle Satellite Telemetry

Scene Overview	{ "summary": "A significant transformation has occurred within the primary port infrastructure, encompassing approximately 7.6% of the total scene. This alteration, identified as a single major cluster, indicates substantial changes in surface characteristics and likely operational layout within the container terminal and adjacent port facilities.", "detailed_analysis": { "scene_overview": "The geographic footprint captures a bustling coastal
Land Cover (LULC)	General remote sensing scene

Spatial Patterns	Standard geographic layout
Spectral Indicators	Visible optical spectrum
Risk & Exposure	No critical hazards detected

Execution Trace & Telemetry Audit

Stage	Status	Detail	Latency
Compatibility Check	OK	Validated 2 image(s) for intent: change_detection	30.0ms
Routing	OK	Intent: change_detection → Selected Specialist: Change Detection	0.0ms
Analyzing	OK	Processed by Siamese DL Engine (Siamese CNN (ONNX)) + Gemini 2.5 Flash	21875.0ms
Building Evidence	OK	Rendered bi-temporal comparative panel with DL contours: [54.7, 19.7,	257.0ms
Confidence Scoring	OK	Raw: 0.87 → High (0.87)	0.0ms