Capitol Manufacturing
1125 Capitol Avenue
Crowley, LA 70526

Phoenix * Capitol * Camco
CapProducts

Commanding a Higher Standard℠

Certified Material Test Report

Printed: 7/15/2026 Certified: 06/25/2026

Customer
ENVIRONMENTAL AND DEWATERING SOI
4266 28TH STREET

DORR ,MI 49323

P.O. STL-330923
Tag
Material
ASTM A106B-2019a / ASME SA106B-2021 Edition

Heat No 0474P
Heat Code 79EG
Order # 103796

4pieces 79EG A/SA106B SCH 80 2

Part Number
15112012TOE

Description
2 X 6" XHSML BK STL NIPL TOE X SQ.CUT DEB

Chemical Properties

C	Mn	P	S	Si	Cu	Ni	Cr
0.1920	0.6350	0.0250	0.0042	0.2130	0.1850	0.0620	0.1260

C Eq. Long
0.3440

Mo	V	Co	Al	Nb	N	Pb	Sn	Ta	Ti
0.0210	0.0016			0.0016					

Additional Chemical Properties

CE CSA
N/A

Cr + Cu + Ni
0.3730

Mechanical Properties

Tensile (PSI)	Yield (PSI)	Elong. % in 2 in. or 4D	R of A %	HBW	HBW2
69293	48940	36		131	133

Charpy Minimum Impact - ft/lbs

Test 1	Test 2	Test 3	Average	Test Temp.	Test Size

Fracture Appearance - %

Test 1	Test 2	Test 3	Average

* Hydro test passed. at 2500 psi.
* Ultrasonic test passed
* Bend test passed.

We hereby certify that these parts were manufactured, sampled, tested, and inspected in accordance with the product specifications stated and were found to meet the requirements.
This document is according to EN 10204 Inspection Certificate 3.1 requirements.
These products meet the requirements of the latest editions of NACE MR0175/ISO 15156 and NACE MR0103. No weld repair has been performed on these products. This material was not exposed to mercury or any other metal alloy that is liquid at ambient temperatures during processing or while in our possession.

Meets ASME SA 106 Grade B Requirements.