



Phoenix * Capitol * Camco CapProducts

Certified Material Test Report

Heat Code: 79ED Heat No: 0475P
Item: 15112006TOE: 2 X 3" XH SMLS TOE X SQ.CUT
Material: ASTM A106B-2019a / ASME SA106B-2021 Edition

Chemistry Properties

C	Mn	P	S	Si	Cu	Cr
0.1850	0.6420	0.0120	0.0032	0.2210	0.1520	0.0920
Ni	Mo	V	Co	Al	Cb	N
0.0620	0.0210	0.0015			0.0016	
Pb	Sn	Ta	Ti	C Eq. Long		
				0.3292		

Additional Chemical Properties

Mechanical Properties

Tensile(PSI)	Yield(PSI)	Elong.% in 2in.or 4D	Reduction	HBW	HBW 2
70303	47987	35%		135	137

Charpy Minimum Impact - ft/lbs ----- Fracture Appearance - ft/lbs

Test 1	Test 2	Test 3	Avg.	Test Temp.	Test Size	Test 1	Test 2	Test 3	Avg.

Bend Test Passed | | Ultrasonic Passed
Hydro Test Passed at 2500 psi

We hereby certify that these parts were manufactured, sampled, tested, and inspected in accordance with the product specifications stated and were found to meet the requirements. This document is according to EN 10204 Inspection Certificate 3.1 requirements. These products meet the requirements of the latest editions of NACE MR0175/ISO 15156 and NACE MR0103. No weld repair has been performed on these products. This material was not exposed to mercury or any other metal alloy that is liquid at ambient temperatures during processing or while in our possession.

Meets ASME SA 106 Grade B Requirements.

Capitol Manufacturing 1125 Capitol Avenue Crowley, LA 70526