

CUENTE / Customer / Client
DODSON GLOBAL, INC
DODSON GLOBAL
2750 Holmes Rd
Houston, TX 77061
2750
USA

CERTIFICADO DE INSPECCION
Inspection Certificate - Certificat de Réception

UNE EN 10204:06 / 3.1
 ISO 10474:15 / 3.1

FECHA: 01/10/2018
 Date:
 N.º 197768
 No.

HOJA: 3
 Page:



SGS 1023164

SGS 0000336

SGS 0000007

ULMA FORJA, S.COOP.

Management Systems certified by LRQA

Certified acc. PED 97/23EC+AD2000-W0
 PED 14/68/EU
 by TÜV Rheinland
 N.º 01 202 EQ 02 7443

EP Zubillaga, 3 - Apdo. 14
 20560 Oñati (Gipuzkoa) SPAIN
 Tel.: 34 - 943 780552
 Fax: 34 - 943 781808
 E-mail: ulma@ulmapiping.com

MARCA DEL FABRICANTE
 Mark of factory
 Marque du fabricant



Packing 142497

PRODUCTO
 Article - Produit

FLANGES

SU PEDIDO N.º
 Your Order No. 210797-00 HOUSTON
 Votre Cde. N.º

DE
 of - de 24/07/2018

NORMAS APLICABLES
 Requirements - Normes Applicables

ASME B16.5-17

MATERIAL CORRESPONDIENTE ASTM A694F52-16

Material Correspondant - Qualité

MODO DE FUSION (*)

Steel Making - Elaboration de l'acier

E = Elec. Y = Origeno básico

NACE MR0175/ISO15156-02/03-15 & NACE MR0103/ISO17485-15

DEPARTAMENTO QUALITY ASSURANCE
 Section
 Département

PARTIDA Item Poste	CANTIDAD Quantity Quantité	DESCRIPCION Description Description	OBSERVACIONES Remarks Observations	COLADA N.º Heat No N.º Coudre	RESISTENCIA T. Strength Reelst Rupt N/mm2	LÍMITE ELAST. Y. Strength 0.2 % N/mm2	ALARGAM. Elongation Lo:50mm/4d %	ESTRACCION Red. Area Striction %	RESILIENCIA Impact test Relliance Joules	CHARPY V 10x10mm		DUREZA Hardness Dureté HBW
										MECA Average Moyenne	°C	
3 B1WRS8-F52	2	WN 8 150LB STD40 RF A694F52	00F18	NE	61MV6	542	378	31,80	49,50			184 164
3 B1WRS8-F52	32	WN 8 150LB STD40 RF A694F52	27L830	NE	A03M8	519	360	41,20	76,70			150 150
17 B9WRS8-F52	12	WN 8 900LB STD40 RF A694F52	19S806	NE	25MV7	523	394	35,50	80,10			178 181

COLADA N.º Heat No N.º Coudre	COMPOSICION QUIMICA - STEEL MAKERS LADLE ANALYSIS - ANALYSE CHIMIQUE															Origin of Steel
	C %	Si %	Mn %	P %	S %	Cr %	Ni %	Mo %	Nb %	V %	Cu %	Al %	Ti %	B %	CEq %	
25MV7	0.172	0.209	1.223	0.012	0.001	0.085	0.062	0.012	0.002	0.066	0.141	0.040	0.001	0.0000	0.42	Italy
61MV6	0.160	0.220	1.240	0.008	0.002	0.080	0.080	0.050	0.004	0.072	0.170	0.030	0.001	0.0003	0.42	Spain
A03M8	0.170	0.230	1.280	0.009	0.006	0.080	0.080	0.014	0.003	0.074	0.170	0.032	0.001	0.0002	0.43	France

- Las dimensiones y la condición superficial se hallaron satisfactorias.
 - Dimension and surface condition were found acceptable.
 - Les dimensions et états de surface sont satisfaisants.

- Los materiales citados cumplen las normas aplicables.
 - Manufacturing requirements are satisfied.
 - Les normes applicables sont respectées.

EL INSPECTOR
 Works Inspector - L'inspecteur



ULMA FORJA S. COOP.
 Dpto. de Garantía de calidad
 Quality Assurance Dept.

(*) OBSERVACIONES:
 Remarks
 Observations

ALL FLANGES MANUFACTURED IN ULMA, SPAIN
 N.º NORMALIZED AT 900 C AND ALLOWED TO COOL IN STILL AIR.

8" WN RF Flange