



Phoenix * Capitol * Camco CapProducts

Certified Material Test Report

Heat Code: **PJD** Heat No: **27080**

Item: 15112006TOE: **2 X 3" XH SMLS TOE X SQ.CUT**

Material: **ASTMA106-2008** / ASME SA106-2007 Edition, No Addenda

Chemistry Properties

C	Mn	P	S	Si	Cu	Cr
0.2100	0.5200	0.0090	0.0050	0.2500	0.2200	0.1100
Ni	Mo	V	Co	Al	Cb	N
0.1100	0.0200	0.0000		0.0000	0.0000	
Pb	Sn	Ta	Ti	C Eq. Long		
				0.3447		

Additional Chemical Properties

Mechanical Properties

Tensile(PSI)	Yield(PSI)	Elong.% in 2in.or 4D	Reduction	HBW	HBW 2
76000	51000	32.5%			

Charpy Minimum Impact - ft/lbs ----- Fracture Appearance - ft/lbs

Test 1	Test 2	Test 3	Avg.	Test Temp.	Test Size	Test 1	Test 2	Test 3	Avg.

Bend Test Passed | | Eddy Current Passed |

We hereby certify that these parts were manufactured, sampled, tested, and inspected in accordance with the product specifications stated and were found to meet the requirements. This document is according to EN 10204 Inspection Certificate 3.1 requirements. These products meet the requirements of the latest editions of NACE MR0175/ISO 15156 and NACE MR0103. No weld repair has been performed on these products. This material was not exposed to mercury or any other metal alloy that is liquid at ambient temperatures during processing or while in our possession.

Meets Hardness Requirments of ISO 15156 latest editions. Meets ASME SA 106 Grade B Requirements.