



Capitol Manufacturing
1125 Capitol Avenue
Crowley, LA 70526

Phoenix * Capitol * Camco
CapProducts

Certified Material Test Report

Commanding a Higher Standardsm

Printed: 5/30/2025

Certified: 02/03/2025

Customer
DNOW LP
1701 GOVER PARKWAY

P.O. 26725599
Tag 3516

Heat No 4700P
Heat Code 79PG
Order # 55476

Material

ASTM A106B-2019a / ASME SA106B-2023 Edition

MOUNT PLEASANT, MI 48858

Part Number
15111012

Description

1 X 6" XHSML BLK NIPL TBE

Chemical Properties

C	Mn	P	S	Si	Cu	Ni	Cr	C Eq. Long	
0.1690	0.6350	0.0135	0.0030	0.2350	0.1250	0.0520	0.0620	0.3041	

Mo	V	Co	Al	Nb	N	Pb	Sn	Ta	Ti
0.0230	0.0021			0.0015					

Additional Chemical Properties

CE CSA
N/A

Cr + Cu + Ni
0.2390

Mechanical Properties

Tensile (PSI)	Yield (PSI)	Elong. % in 2 in. or 4D	R of A %	HBW	HBW2
70886	45640	33.66		123	124

Charpy Minimum Impact - ft/lbs

Fracture Appearance - %

Test 1	Test 2	Test 3	Average	Test Temp.	Test Size	Test 1	Test 2	Test 3	Average

* Hydro test passed. at 2500 psi.

* Eddy Current test passed

* Bend test passed.

We hereby certify that these parts were manufactured, sampled, tested, and inspected in accordance with the product specifications stated and were found to meet the requirements.

This document is according to EN 10204 Inspection Certificate 3.1 requirements.

These products meet the requirements of the latest editions of NACE MR0175/ISO 15156 and NACE MR0103. No weld repair has been performed on these products. This material was not exposed to mercury or any other metal alloy that is liquid at ambient temperatures during processing or while in our possession.

Meets ASME SA 106 Grade B Requirements.