

150

**Capitol Manufacturing**

1125 Capitol Avenue

Crowley, LA 70526

Phoenix * Capitol * Camco**CapProducts****Certified Material Test Report***Commanding a Higher Standard™*

Printed: 5/17/2024

Certified: 06/06/2023

Customer

P.O. 662461566

Heat No 7813N

DNOV LP

Tag 740463

Heat Code 797G

1701 GOVER PARKWAY

Material

Phoenix Order # 16034

ASTM A106B-2019a / ASME SA106B-2021 Edition

MOUNT PLEASANT, MI 48858

Part Number

Description

15112006TOE

2 X 3" XH SMLS TOE X SQ.CUT

Chemical Properties

C	Mn	P	S	Si	Cu	Ni	Cr	C Eq. Long	
0.1640	0.6300	0.0130	0.0050	0.2200	0.0160	0.0500	0.1100	0.3007	
Mo	V	Co	Al	Nb	N	Pb	Sn	Ta	Ti
0.0250	0.0015			0.0018					

Additional Chemical Properties

					CE CSA	Cr + Cu + Ni
					N/A	0.1760

Mechanical Properties

Tensile (PSI)	Yield (PSI)	Elong. % in 2 in. or 4D	R of A %	HBW	HBW2
67814	45313	35.7			

Charpy Minimum Impact - ft/lbs**Fracture Appearance - %**

Test 1	Test 2	Test 3	Average	Test Temp.	Test Size	Test 1	Test 2	Test 3	Average

* Hydro test passed. at 2500 psi.

* Ultrasonic test passed

* Bend test passed.

We hereby certify that these parts were manufactured, sampled, tested, and inspected in accordance with the product specifications stated and were found to meet the requirements.

This document is according to EN 10204 Inspection Certificate 3.1 requirements.

These products meet the requirements of the latest editions of NACE MR0175/ISO 15156 and NACE MR0103. No weld repair has been performed on these products. This material was not exposed to mercury or any other metal alloy that is liquid at ambient temperatures during processing or while in our possession.

Meets ASME SA 106 Grade B Requirements.