



# Phoenix \* Capitol \* Camco CapProducts

## Certified Material Test Report

Heat Code: 79EF Heat No: 0476P

Item: 15112012TOE: 2 X 6" XHSM BK STL NIPL TOE X SQ.CUT DEB

Material: ASTM A106B-2019a / ASME SA106B-2021 Edition

### Chemistry Properties

|        |        |        |        |            |        |        |
|--------|--------|--------|--------|------------|--------|--------|
| C      | Mn     | P      | S      | Si         | Cu     | Cr     |
| 0.1630 | 0.6210 | 0.0150 | 0.0042 | 0.2210     | 0.1820 | 0.1230 |
| Ni     | Mo     | V      | Co     | Al         | Cb     | N      |
| 0.0620 | 0.0210 | 0.0015 |        |            | 0.0014 |        |
| Pb     | Sn     | Ta     | Ti     | C Eq. Long |        |        |
|        |        |        |        | 0.3119     |        |        |

### Additional Chemical Properties

|  |  |  |  |  |
|--|--|--|--|--|
|  |  |  |  |  |
|  |  |  |  |  |

### Mechanical Properties

|              |            |                      |           |     |       |
|--------------|------------|----------------------|-----------|-----|-------|
| Tensile(PSI) | Yield(PSI) | Elong.% in 2in.or 4D | Reduction | HBW | HBW 2 |
| 70971        | 49125      | 36%                  |           | 132 | 134   |

### Charpy Minimum Impact - ft/lbs ----- Fracture Appearance - ft/lbs

|        |        |        |      |            |           |        |        |        |      |
|--------|--------|--------|------|------------|-----------|--------|--------|--------|------|
| Test 1 | Test 2 | Test 3 | Avg. | Test Temp. | Test Size | Test 1 | Test 2 | Test 3 | Avg. |
|        |        |        |      |            |           |        |        |        |      |

Bend Test Passed | | Ultrasonic Passed

Hydro Test Passed at 2500 psi

We hereby certify that these parts were manufactured, sampled, tested, and inspected in accordance with the product specifications stated and were found to meet the requirements. This document is according to EN 10204 Inspection Certificate 3.1 requirements. These products meet the requirements of the latest editions of NACE MR0175/ISO 15156 and NACE MR0103. No weld repair has been performed on these products. This material was not exposed to mercury or any other metal alloy that is liquid at ambient temperatures during processing or while in our possession.

Meets ASME SA 106 Grade B Requirements.

Capitol Manufacturing 1125 Capitol Avenue Crowley, LA 70526