



Capitol Manufacturing
1125 Capitol Avenue
Crowley, LA 70526

Phoenix * Capitol * Camco
CapProducts

Certified Material Test Report

Commanding a Higher Standardsm

Printed: 5/5/2026

Certified: 06/02/2023

Customer
DNOV LP
1701 GOVER PARKWAY

P.O. 662974043
Tag 103942

Heat No 7936
Heat Code 7936
Order # 95311

Material
ASTM A234-2019 WPB / ASME SA234-2021 Edition

MOUNT PLEASANT ,MI 48858

Part Number
48100049

Description
3X1/2 XH WPB CONC SWG TBE

Chemical Properties

C	Mn	P	S	Si	Cu	Ni	Cr	C Eq. Long	
0.1900	1.0400	0.0050	0.0170	0.2100	0.0300	0.0100	0.1200	0.3926	

Mo	V	Co	Al	Nb	N	Pb	Sn	Ta	Ti
0.0100	0.0030			0.0110	0.0024				

Additional Chemical Properties

					CE CSA		Cr + Cu + Ni	
					N/A		0.1600	

Mechanical Properties

Tensile (PSI)	Yield (PSI)	Elong. % in 2 in. or 4D	R of A %	HBW	HBW2
73900	41200	37	66	143	144

Charpy Minimum Impact - ft/lbs

Fracture Appearance - %

Test 1	Test 2	Test 3	Average	Test Temp.	Test Size	Test 1	Test 2	Test 3	Average

We hereby certify that these parts were manufactured, sampled, tested, and inspected in accordance with the product specifications stated and were found to meet the requirements.

This document is according to EN 10204 Inspection Certificate 3.1 requirements.

These products meet the requirements of the latest editions of NACE MR0175/ISO 15156 and NACE MR0103. No weld repair has been performed on these products. This material was not exposed to mercury or any other metal alloy that is liquid at ambient temperatures during processing or while in our possession.

Manufactured in the USA.