RMS record

Location information

Location: Zgrada Ivana Gundulića 12a, ulaz B
Address: Ulica Ivana Gundulića 12a, 51000 Rijeka
Contact person: Marko Horvat
Phone: +385 91 123 4567

Technicians

Primary technician: Ivo Ivić
Second technician: Ana Anić

Service data

Service date: 04/11/2026
Created time: 10:15:30
Status: O.K.

Notes

Zamijenjen kontaktor i provjerena sigurnosna petlja. Replaced the contactor and verified the safety circuit on both cars; customer informed. Zamijenjen kontaktor i provjerena sigurnosna petlja. Replaced the contactor and verified the safety circuit on both cars; customer informed. Zamijenjen kontaktor i provjerena sigurnosna petlja. Replaced the contactor and verified the safety circuit on both cars; customer informed.

Items by elevator

- Lift A: O.K.
- Lift B: Repair required - elevator in service - Škripi vrata
- Lift C: Repair required - elevator out of service

Signatures

Technician signature:

Name: Ivo Ivić
Date: 04/11/2026

Client signature:

Name: _____
Date: 04/11/2026