



# MagAsyst

Your partner in buissnes

### Login

Username\*

admin

Password\*

••••

Login

WarehouseApp

localhost:4200/dash/admindash

admin

MagAsyst 1.0

Dashboard

All users

All equipment

Report of inspection

Equipment

Quantity

5

More

Users

Quantity

5

More

Inspections

Last inspection

02-09-2024

More

Inspections

Errors

0

More

## Reports

Report of inspections

+ Add inspection

Id	Date	Eq. name	Model	Serial number	Reg. Name	Familly name	Division	Position	Body	Wheel	Brake	Light	Horn	Belt	Leak	Battery	Status	Comments	Actions
----	------	----------	-------	---------------	-----------	--------------	----------	----------	------	-------	-------	-------	------	------	------	---------	--------	----------	---------

🔄 Get Inspection

# Reports

Report of inspections

+ Add inspection

Id Date		Eq. name	Model	Serial number	Reg.	Name	Family name	Division	Position	Body	Wheel	Brake	Light	Horn	Belt	Leak	Battery	Status	Comments	Actions	
1	02-09-2024	PPT	120	EW111	1	Adam	Nowak	Warehouse	Operator	ok	ok	ok	ok	ok	ok	ok	ok	ok		Edit	Delete
2	02-09-2024	PPT	120	EW121	2	Robert	Szota	Warehouse	Operator	ok	ok	ok	ok	ok	ok	ok	ok	ok		Edit	Delete
3	02-09-2024	PPT	120	EW122	3	Ewa	Ogrodnik	Warehouse	Operator	ok	ok	ok	ok	ok	ok	ok	ok	ok		Edit	Delete

🔄 Get Inspection

WarehouseApp

localhost:4200/dash/add-inspection

admin

--Select--

Hours

Status body

okNOK

Status lights

okNOK

Status breaks

okNOK

Status wheels

okNOK

Status horn

okNOK

Status belts

okNOK

Status leaks

okNOK

Status battery

okNOK

Comments

Add Raport



admin



14 RT ZW10 310 Hours

Status body

☒ Ok ☐ NOK

Status lights

☒ Ok ☐ NOK

Status breaks

☒ Ok ☐ NOK

Status wheels

☒ Ok ☐ NOK

Status horn

☒ Ok ☐ NOK

Status belts

☒ Ok ☐ NOK

Status leaks

☒ Ok ☐ NOK

Status battery

☐ Ok ☒ NOK

no battery charging

Add Raport

<div>Equipment</div> <div>Quantity</div> <div>5</div> <div>More</div>	<div>Users</div> <div>Quantity</div> <div>5</div> <div>More</div>	<div>Inspections</div> <div>Last inspection</div> <div>02-10-2024 09:08:40 AM</div> <div>More</div>	<div>Inspections</div> <div>Errors</div> <div>1</div> <div>More</div>
---	---	---	---

Reports

Raport of inspections

+ Add inspection

Id	Date	Eq. name	Model	Serial number	Reg.	Name	Family name	Division	Position	Body	Wheel	Brake	Light	Horn	Belt	Leak	Battery	Status	Comments	Actions
1	02-09-2024	PPT	120	EW111	1	Adam	Nowak	Warehouse	Operator	ok	ok	ok	ok	ok	ok	ok	ok	ok		<div>EditDelete</div>
2	02-09-2024	PPT	120	EW121	2	Robert	Szota	Warehouse	Operator	ok	ok	ok	ok	ok	ok	ok	ok	ok		<div>EditDelete</div>
3	02-09-2024	PPT	120	EW122	3	Ewa	Ogrodnik	Warehouse	Operator	ok	ok	ok	ok	ok	ok	ok	ok	ok		<div>EditDelete</div>
4	02-10-2024 09:08:40 AM	RT	310	ZW10	4	Adam	Nowak	Warehouse	Operator	Ok	Ok	Ok	Ok	Ok	Ok	Ok	Nok	Nok	Equipment failure: no battery charging	<div>EditDelete</div>

Get Inspection