



Location Information

Safelite 302 W BELTLINE HWY MADISON, WI 53713 608-258-3333

Account Information

CONSUMER PARENT 92273 - 085080 --

Deductible - Invoice

05176-346301

Technician 01867-759

Inv Date: 7/23/2025 CTU WO: 714415

Installation Completed: 7/23/2025 10:13 AM 143-01867-759-714415-T

MIKE PENNEKAMP 3268 Siggelkow Rd Mc Farland, WI 53558

Primary: 608-209-5606

Policy #:

Alternate: 608-209-5606 Claim #: PO#/Ref: Ath/Ver:

Loss Loc:

Loss Date/Cause:

Year	Make	Model		Boo	ly Style	!		Mileage	License	State Stock#	
2025	CHEVROLET	SILVERADO 2500	2 DOOR STANDARD CAB		CAB	2000.00 RP6	RP6887	WI			
Vehicle I	D#: 1 G 3 C F	K L E 7 X	S F	1	1 2	8 7	0	Service Lo	cation: Mobile		
Qty	Part #		List		Sell	ling		Labor	Kit	Material	Extension
1	MWSREPAIR				\$0	0.00	\$	164.99	\$0.00	\$0.00	\$164.99
Replace	with new - MOBILE WIN	NDSHIELD REPAIR:									
1	MOBILE FEE WSR				\$0	0.00		\$0.00	\$0.00	\$0.00	\$0.00
Replace	with new - MOBILE FEE	REPAIR									
1	SUPPLIES-REPAIR				\$7	7.99		\$0.00	\$0.00	\$0.00	\$7.99
Replace	with new - REPAIR SUPI	PLIES:									

Comment:

Tender Information

 Type
 Card Type
 Account
 Auth Code
 Amount

 Credit
 MC
 xxxx-xxxx-xxxx-2093
 47964Z
 \$182.49

Initial here if replaced parts should be saved for inspection or returned:	
Part Sub Total:	\$7.99
Labor Sub Total:	\$164.99
Sub Total:	\$172.98
Sales Tax:	\$9.51
Total	\$182.49
Total Balance Due	\$0.00



Product Name:

7 4 1 8 5 2 9 6 3

manufactured by Safelite AutoGlass or another after policy to recover, and authorize my insurance comp any unpaid balance.	rmarket manufacturer. Subjec	t to completion of the work,	,	have under my insurance
Customer's Signature:		Date:		
If your check is unpaid for insufficient or uncollected the right to select the repair facility of your choice.	funds, we may electronically of	debit your account for the pr	inciple check amount and a service fee as a	llowable by law. You have
Revised Estimate:	Reason:		Additional Cost:	
Authorized by:	Phone:	Date:	Time:	
Amount to collect from Customer: \$0.00	Tender:			
Lot #:			Safe to drive after:	AM PM
Adhesive Brand:				