



Sprint Assessors
1 Cherrytree Crescent
Salford Priors
Nr Evesham
Worcestershire

WR11 5XF

29/07/25

Our Ref: 28421/HS/HS

Client: Mr Ahmed
Vehicle: KM72BUE/Toyota Prius
Incident Date: 11/04/2025

Dear Sirs

Please arrange an inspection of the client's vehicle to take place within the next 48 working hours and provide a report detailing the damage sustained, costs of repair, or cost of replacement if beyond repair.

The Current Status of Vehicle:

The Current Location of Vehicle: Newcastle Repair Centre,

Unit
Condercum Road,

D

New Castle upon Tyne,

Contact: 07727108562 (Ehsaan)

NE4 8XQ

If the vehicle is at the Client's address please contact the Client to arrange the inspection. Contact details are listed below.

We would be grateful if you could confirm when the inspection will be taking place once it has been arranged. If the inspection cannot be carried out within the next 48 working hours, please notify us immediately.

We look forward to receiving your report.

Hina Sadaf
FNOL AND ROADWORTHY HANDLER
Nationwide Assist Ltd



	T: 0121 766 7515 W: https://www.camsgroup.uk/ 25-39 Small Heath Highway A: Birmingham B10 0EU	New Claim Advice Ref: 28421
		Driver Non-Fault Accident Report Form

DRIVER DETAILS

Name:	Mr Hassan Ahmed	Address:	106 Wingrove Gardens Newcastle Upon Tyne
Phone No:			
Work No:			
Mobile No:	07454004468	Postcode:	NE4 9HR
Date of Birth:	02/08/1990	National Insurance No.:	NJ759297B
Email Address:			
Are you claiming any benefits?		If Yes, What benefits?	
Insurance Co:			
Address:		Policyholder's Name:	
Do you have legal expense cover?		Policy Number:	
Accident reported to your Insurance Co:		Claim Ref No:	

VEHICLE DETAILS

Make:	Toyota	Model:	Prius	Registration:	KM72BUE
Type of Insurance:		Policy Excess:	£0		
Area & Extent of Damage:	Front Nearside: no Middle Nearside: no Rear Nearside: no Front Offside: no Middle Offside: no Rear Offside: no Rear: no Front: no			Current Vehicle Status:	
Is your Vehicle in use?		Estimated value of your vehicle:			
Have you hired a replacement vehicle?		If yes, from whom?			
Vehicle Location?	Newcastle Repair Centre,				

DETAILS OF THIRD PARTY

Name:	Mr	Address:	Fled The Scene/ Hit And Run
--------------	----	-----------------	-----------------------------



Phone No:			
Work No:			
Mobile No:		Post Code:	
Their Vehicle:	vauxhall Cdti	insignia Sri Reg. No:	NA10OYB Colour
Insurance Co:	Axa Insurance Uk Plc 0345 608 0230	Policy No:	303610628
		ClaimRef:	2000899806

ACCIDENT DETAILS

Date:	11/04/2025	Time:	01:00 - 02:00	Location:	Ponteland Road Roundabout
Did Police Attend?		Police Details:			

Brief Description and / or Sketch:

Tpv Collided With My Car At Rab, And Then Fled The Scene, I Followed Him Toward Springfield Road Where He Entered A Close Street And Hit Another Parked Vehicle. He Then Abandoned His Car And Ran Away

TRAFFIC, WEATHER & ROAD CONDITIONS

Weather conditions:		Road conditions:	
Level of Traffic:		How many vehicles involved?	

OTHER LOSSES

Are you registered for VAT?		
Name:		
Address:		
Postcode:		Payroll No:

DECLARATION

I confirm that the information that I have provided is true and accurate. I am also aware that if I provide false, inaccurate or misleading information, not only could I prejudice the claim, but I may also be liable for the costs incurred by Central Accident Management Services Limited.

Client's Signature:		Date:	
---------------------	--	-------	--

HEAD OFFICE: Nationwide Assist Ltd 25-39 Small Heath Highway Birmingham B10 0EU
Tel: 0121 766 7515