
SAMPLE ELEMENTARY SCHOOL - SAMPLE ISD

Stored Material Documentation - Pay Application No. 1 (Period 02/01/2026 to 02/28/2026)

Div 23 HVAC Material: rooftop unit package, Sample Supply quote Q-1001, PO-1001 ($10,000.00)




File: IMG_0001.JPG | Captured: March 2, 2026 8:00 AM CST | GPS: 0.000100, 0.000100

Capture date, time, and GPS coordinates per embedded image metadata (EXIF, phone camera).
Location: Sample Elementary School campus, 200 Example Avenue, Anytown, TX 75001 (on-site delivery). GPS coordinates are consistent with the project site.
Delivery truck staged at the campus drive with the new rooftop units strapped on the flatbed, before the first pick.

SAMPLE ELEMENTARY SCHOOL - SAMPLE ISD

Stored Material Documentation - Pay Application No. 1 (Period 02/01/2026 to 02/28/2026)
Div 23 HVAC Material: rooftop unit package, Sample Supply quote Q-1001, PO-1001 ($10,000.00)




File: IMG_0002.JPG | Captured: March 2, 2026 8:02 AM CST | GPS: 0.000150, 0.000120

Capture date, time, and GPS coordinates per embedded image metadata (EXIF, phone camera).
Location: Sample Elementary School campus, 200 Example Avenue, Anytown, TX 75001 (on-site delivery). GPS coordinates are consistent with the project site.
New rooftop unit field-marked RTU-1 on the flatbed. Shipping label visible.

SAMPLE ELEMENTARY SCHOOL - SAMPLE ISD

Stored Material Documentation - Pay Application No. 1 (Period 02/01/2026 to 02/28/2026)

Div 23 HVAC Material: rooftop unit package, Sample Supply quote Q-1001, PO-1001 ($10,000.00)



File: IMG_0003.JPG | Captured: March 2, 2026 8:03 AM CST | GPS: 0.000150, 0.000120

Capture date, time, and GPS coordinates per embedded image metadata (EXIF, phone camera).
Location: Sample Elementary School campus, 200 Example Avenue, Anytown, TX 75001 (on-site delivery). GPS coordinates are consistent with the project site.
Unit data plate for RTU-1: model and serial number legible, matching the approved submittal. Confirms new, contract-specified equipment.