



HOLIDAY TEST REPORT

REPORT NO

780 / HTR / EPOKTR / 2025

DATE

20-06-2025

AREA

PT. UNGGUL BRATA

Page

1 of 2

Weather

Bright

Cloudy

Rain

✓


A. ACTIVITY

No.	KP	Joint No.	Length (M)	Field Joint Coating Status	Voltage	Visual Inspection	Remarks
1	183	.	12.010	ACC	15KV	ACC	
2	183	M-60	12.030	ACC	15KV	ACC	
3	183	.	12.020	ACC	15KV	ACC	
4	183	M-69	12.020	ACC	15KV	ACC	
5	183	M-70	12.690	ACC	15KV	ACC	
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							

TOTAL (pcs / m)

5 Pcs / 60-770 mm

Perform by :
KSO TIMAS - PRATIWI


(RIDUT SANTOSO)

Witness / Approved by,
MK


(A. Lihorainy)



PEMBANGUNAN PIPA TRANSMISI GAS BUMI CIREBON-SEMARANG TAHAP 2
(RUAS BATANG – CIREBON – KANDANG HAUR TIMUR)



HOLIDAY TEST REPORT

Report No. : 780/HTR/02/EPC/KTP/VI/2025

Area : _____

Date : 20-Jun-25

Pipe Size : Ø 20 Inch


Page : 3 of 3

Weather :

Bright	Cloudy	Rain

Time : _____

DOKUMENTASI





HOLIDAY TEST REPORT

REPORT NO

26. INTRINSIKTRIP 2025

DATE

20.06.2025

AREA

PT. SEMANGAT

Page

1 of 2

Weather

Bright

Cloudy

Rain

A. ACTIVITY

No.	KP	Joint No.	Length (M)	Field Joint Coating Status	Voltage	Visual Inspection	Remarks
1	155		12.220	Acc	15 KV	Acc	
2	155	HDD-74	12.370	Acc	15KV	Acc	
3	155	HDD-75	12.300	Acc	15KV	Acc	
4	155	HDD-76	12.370	Acc	15KV	Acc	
5	155	HDD-77	12.300	Acc	15KV	Acc	
6	155	HDD-78	12.000	Acc	15KV	Acc	
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							

TOTAL (pcs / m)

GRs / 73.830 m

Perform by :
KSO TIMAS - PRATIWI


RIFUT SANTOSO

Witness / Approved by,
MK


A. Khuzaini



PEMBANGUNAN PIPA TRANSMISI GAS BUMI CIREBON-SEMARANG TAHAP 2
(RUAS BATANG - CIREBON - KANDANG HAUR TIMUR)



HOLIDAY TEST REPORT

Report No. 38/JHTR/02/EPC/KTP/VI/2025

Area

Date : 20-Jun-25

Pipe Size

Ø 20 Inch

Page

3 of 3

Weather


Bright

Cloudy

Rain

Time

DOKUMENTASI





HOLIDAY TEST REPORT

REPORT NO

26. JKTREPOKTRIP 02815

DATE

20.06.2025

AREA

PT. SEMANGAT

Page

1 of 2

Weather

Bright

Cloudy

Rain

A. ACTIVITY

No.	KP	Joint No.	Length (M)	Field Joint Coating Status	Voltage	Visual Inspection	Remarks
1	155		12.220	Acc	15 KV	Acc	
2	155	HDD-74	12.370	Acc	15KV	Acc	
3	155	HDD-75	12.300	Acc	15KV	Acc	
4	155	HDD-76	12.370	Acc	15KV	Acc	
5	155	HDD-77	12.300	Acc	15KV	Acc	
6	155	HDD-78	12.000	Acc	15KV	Acc	
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							

TOTAL (pcs / m)

GRs / 73.830 m

Perform by :
KSO TIMAS - PRATIWI


RIFU7 SANTOSO

Witness / Approved by,
MK


A. Khuzaini



PEMBANGUNAN PIPA TRANSMISI GAS BUMI CIREBON-SEMARANG TAHAP 2
(RUAS BATANG - CIREBON - KANDANG HAUR TIMUR)



HOLIDAY TEST REPORT

Report No. 38/JHTR/02/EPC/KTP/VI/2025

Area

Date : 20-Jun-25

Pipe Size

Ø 20 Inch

Page

3 of 3

Weather

Bright

Cloudy

Rain

Time

DOKUMENTASI

