

MAINTENANCE WORK ORDER ARCHIVE

Generated from sealed ledger transaction

MWO ID: MWO-2026-102
STATUS: COMPLETED
ASSIGNED TECH: U-001
EQUIPMENT ID: EQ-03
COMPLETED AT: 2026-04-29T19:59:25.878448+00:00
LABOR HOURS: 2.5

DESCRIPTION:

Fluid leak on hydraulic press

RESOLUTION NOTES:

Replaced faulty contactor. Verified 24V circuit integrity under load. System nominal.

CONSUMED PARTS LEDGER

TXN ID	PART ID	QTY	TECH	TIMESTAMP
TXN-PROOF-9F3057	PRT-002	1	TECH-02	2026-04-29 19:19:18
TXN-9FA0CCBB	PRT-002	3	U-001	2026-04-29 19:38:28