

MAINTENANCE WORK ORDER ARCHIVE

Generated from sealed ledger transaction

MWO ID: RFK26-MWO-05-059

STATUS: COMPLETED

ASSIGNED TECH: U-B9A624

EQUIPMENT ID: EQ-6266A8

EQUIPMENT DESC: Enrober 1

COMPLETED AT: 1781231116.4194412

LABOR HOURS: 0.078222749431928

DESCRIPTION:

The chocolate does not flow properly down the enrober

RESOLUTION NOTES:

fix it!