

MOTOR INSURANCE CLAIM FORM		OWN DAMAGE
Claim No.: DP-2026-002104	Type: DP — OWN DAMAGE	Insurer: Seguros Meridiano, S.A.

STATUS: UNDER INVESTIGATION

1. POLICYHOLDER INFORMATION	
Full Name:	María Fernanda Castillo Ureña
ID / Cédula:	002-3456789-1
Date of Birth:	July 22, 1990
Address:	Calle Las Damas 17, Zona Colonial, Santo Domingo, D.N.
Phone:	+1 (829) 667-4421
Email:	mfcastillo@correo.do
Policy Number:	POL-SDQ-2023-056118
Coverage Type:	Comprehensive (All-Risk)
Deductible:	DOP 20,000

2. INSURED VEHICLE	
Make / Model:	Kia Sportage EX
Year:	2021
Color:	Midnight Black
License Plate:	C-778812
VIN / Chassis:	KNDP63AC6M7234561
Declared Value:	DOP 1,780,000
Odometer (at loss):	51,880 km

3. INCIDENT DETAILS	
Incident Date:	May 22, 2026
Incident Time:	Between 21:00 and 23:30 (estimated)
Location:	Parking garage — Centro Comercial Agora Mall, Av. John F. Kennedy, Santo Domingo
Discovery Date/Time:	May 22, 2026, 23:31 (upon return to vehicle)
CCTV Available:	Yes — mall security confirms footage available for Level 3, Zone B
Police Report No.:	PN-SDQ-2026-051089

4. INCIDENT NARRATIVE

The insured parked her vehicle on Level 3, Zone B of the Agora Mall parking garage at approximately 21:00 on May 22, 2026 while attending a social event inside the mall. Upon returning to the vehicle at 23:31, she discovered that all four tires had been slashed, both side mirrors had been broken off, and extensive key scratches had been made along both lateral doors and the hood. No window was broken and no items were taken from the interior. The insured immediately notified mall security, who confirmed that CCTV cameras cover the area. Police arrived and filed report No. PN-SDQ-2026-051089. The vehicle remains immobile in the mall parking garage pending tow authorization from the insurer.

5. DAMAGE ASSESSMENT		
Part / Component	Damage	Est. Cost (DOP)
4x tires (225/55 R18)	All four slashed — full replacement	68,000
Left side mirror	Broken off at base — replacement + repaint	14,500
Right side mirror	Broken off at base — replacement + repaint	14,500
Driver-side door	Deep key scratch full-length — repaint	22,000
Passenger-side door	Deep key scratch — repaint	22,000
Hood	Circular scratch pattern — repaint	19,500
Labor	~22 man-hours	19,800
TOTAL ESTIMATE		180,300

6. DOCUMENTS SUBMITTED

- Vehicle registration and marbete
- Policyholder national ID (cédula)
- Driver's license
- Police report No. PN-SDQ-2026-051089
- 8 photographs of damage (tires, mirrors, scratches)
- Mall security incident report — reference MGA-SEC-20260522-089
- Workshop estimate — Bodywork Express Piantini
- CCTV footage request acknowledgment from Agora Mall security

7. INVESTIGATOR NOTE

STATUS: Under Investigation. CCTV footage has been requested from Agora Mall. Adjuster to verify footage retrieval and confirm vandalism is not excluded under policy clause 14.3 (intentional acts by known parties). Expected resolution: 7–10 business days.

Policyholder Signature

Date

Claims Investigator