

TIME SPENT



0h:0m

COMPLETED ON

Saturday 20th April 2019

ARRIVED ON SITE

15:53

<div><div>✓</div><div>Take picture before service</div><div></div></div>
<div><div>✓</div><div>Use air blower</div><div></div></div>
<div><div>✓</div><div>Spot removing from ATM Area</div><div></div></div>
<div><div>✓</div><div>Clean ATM Glass shade with Glass Cleaner</div><div></div></div>
<div><div>✓</div><div>Remove any gums from ATM area</div><div></div></div>
<div><div><div>☐</div></div><div>Clean ATM Keyboard with Polisher</div><div></div></div>
<div><div>✓</div><div>Wipe all ATM with microfiber cloth</div><div></div></div>
<div><div>✓</div><div>Empty waste bin</div><div></div></div>
<div><div><div>☐</div></div><div>Take photo for any damage</div><div></div></div>
<div><div><div>✓</div></div><div>Take photo after service</div><div></div></div>