











## 1. SCREEN



SCREEN NAME	PC NAME	PLAYER ID	NET CABLE NAME CONNECTED TO PC	PATCH PORT	SWITCH PORT	LED SCREEN FUSE	PC FUSE	AUTO POWER CUT (CLOCK/STORE ALARM)
LED_TECHPANEL_WOMAN_OF_S1	V309C232CEE4A	700455862	VWALL1	67	21	QF28	QF19	Store
LED_TECHPANEL_MAN_OF_S2	V309C232CED93	700455861	VWALL2	70	20	QF29	QF19	Store
LED_TECHPANEL_WOMAN_OF_S3	V309C232CEE05	700455863	VWALL3	72	23	QF30	QF19	Store



## 1.1. SCREEN PICTURES


SCREEN NAME	SCREEN PICTURE	PC/SENDER BOX PICTURE	SCREEN BRIGHTNESS - 30%	COMENTS
LED_TECHPANEL_WOMAN_OF_S1			YES	

SCREEN NAME	SCREEN PICTURE	PC/SENDER BOX PICTURE	SCREEN BRIGHTNESS - 30%	COMENTS
LED_TEHPANEL_MAN_OF_S2			YES	A fecha de apertura está pendiente la recepción de una sending para S2, por lo que se deja conectada a la S3. Se modificará tras la recepción de la sending
LED_TEHPANEL_WOMAN_OF_S3			YES	
SCREEN NAME	SCREEN FUSE PICTURE	COMENTS	PC FUSE PICTURE	COMENTS


SCREEN NAME	SCREEN FUSE PICTURE	COMENTS	PC FUSE PICTURE	COMENTS
LED_TECHPANEL_WOMAN_OF_S1				
LED_TECHPANEL_MAN_OF_S2				

SCREEN NAME	SCREEN FUSE PICTURE	COMENTS	PC FUSE PICTURE	COMENTS
LED_TECHPANEL_WOMAN_OF_S3				


SCREEN NAME	CONNECTION TEST PICTURE	COMENTS
LED_TECHPANEL_WOMAN_OF_S1		IP 10.167.167.179
LED_TECHPANEL_MAN_OF_S2		IP 10.167.167.178

SCREEN NAME	CONNECTION TEST PICTURE	COMENTS
LED_TECHPANEL_WOMAN_OF_S3		IP 10.167.167.192



2. AUDIO

2.1. SHOP SPEAKER PICTURE	COMENTS
	


2.2. FITTING ROOM SPEAKER PICTURE		COMENTS
		
2.3. STORE ROOM SPEAKER PICTURE	COMENTS	
	No se montan altavoces	
2.4. VOLUME CONTROL PICTURE	COMENTS	
	No se monta	
2.5. MICROPHONE PICTURE	COMENTS	
		

2.6. AUDIO RACK PICTURE	COMENTS	
		Falta por llegar el hilo musical
2.7. MIXER PICTURE		COMENTS
		







2.8. AMPLIFIERS PICTURES		COMENTS
		
2.9. RACK FUSE PICTURE		COMENTS
		
2.10. MUSIC PLAYER CONNECTION TEST PICTURE		COMENTS
		No ha llegado



2.11. MUSIC PLAYER 24H FUSE PICTURE	COMENTS
	QF 19
2.12. MUSIC PLAYER SERIAL NUMBER PICTURE	COMENTS
	No ha llegado

### 3. RACK

3.1. RACK GENERAL VIEW	COMENTS
	
3.2. PATCH PICTURE	COMENTS
	

3.3. SWITCH PICTURE		COMENTS
		
3.4. FUSES RACK DOCUMENTATION PICTURE		COMENTS
		
3.5. RACK DOCUMENTATION PICTURE	COMENTS	
	No ha llegado documentación con el rack	

## 4. GENERAL

4.1. FUSES GENERAL VIEW	COMENTS
	
4.2. SPARE PARTS PICTURE	COMENTS
	<p>Queda ubicado en una sala frente al rack</p>

