Brackenfield Analytical Laboratories
12 Foundry Yard, Brackenfield BK4 6RW
Telephone 01632 960771 · lab@brackenfield-analytical.example

Water Quality Test Report

Client
Ashcombe Parish Council
The Old School Room
Church Lane, Ashcombe
Wexford Vale WV7 2LP

Sample details

Report number	WQ-25-03318
Sample ID	S-114207
Sample point	Village hall, kitchen tap
Sampled	3 March 2025, 09:40
Received	3 March 2025, 14:15
Sample type	Mains drinking water

Summary

The sample complied with the drinking water standards for all the parameters tested, except for lead. The lead concentration of 14 µg/L exceeds the prescribed limit of 10 µg/L. This is most likely caused by lead pipework within the building rather than by the public supply.

Microbiological results

Parameter	Result	Unit	Limit	Method	Compliance
Coliform bacteria	0	per 100 mL	0	MB-02 membrane filtration	Pass
Escherichia coli	0	per 100 mL	0	MB-02 membrane filtration	Pass
Enterococci	0	per 100 mL	0	MB-05 membrane filtration	Pass
Colony count at 22 °C	14	per mL	No abnormal change	MB-07 pour plate	Pass

Physical and chemical results

Parameter	Result	Unit	Limit	Method	Compliance
pH	7.6	pH units	6.5–9.5	CH-01 electrometric	Pass
Conductivity at 20 °C	412	µS/cm	2500	CH-02 conductimetric	Pass
Turbidity	0.21	NTU	4	CH-03 nephelometric	Pass
Colour	<2	mg/L Pt/Co	20	CH-04 spectrophotometric	Pass
Nitrate	18.3	mg/L	50	CH-11 ion chromatography	Pass

Nitrite	<0.01	mg/L	0.5	CH-11 ion chromatography	Pass
Fluoride	0.12	mg/L	1.5	CH-12 ion chromatography	Pass
Iron	31	µg/L	200	ME-01 ICP-MS	Pass
Manganese	<2	µg/L	50	ME-01 ICP-MS	Pass
Copper	0.18	mg/L	2.0	ME-01 ICP-MS	Pass
Lead	14	µg/L	10	ME-01 ICP-MS	**Fail**
Nickel	3	µg/L	20	ME-01 ICP-MS	Pass
Aluminium	12	µg/L	200	ME-01 ICP-MS	Pass

Interpretation and advice

Lead can accumulate in water that stands in lead pipes, and young children and pregnant women are most at risk. We recommend the following actions while the source of the lead is investigated.

- Run the kitchen tap for at least two minutes before drawing water for drinking or cooking, especially after the building has been unused overnight.
- Use only the kitchen tap for drinking water until the pipework has been surveyed.
- Ask a plumber to identify and replace any lead pipes or fittings between the stopcock and the kitchen.
- Request a follow-up sample after any remedial work.

A repeat sample taken after flushing would show whether the lead comes from water standing in the pipes.

Notes on methods

Limits are the prescribed concentrations or values for water intended for human consumption. Results reported as < are below the limit of quantification. All samples were kept chilled and analysed within 24 hours of collection.

Authorised by: Helen Marchetti, Laboratory Manager
Date of issue: 10 March 2025