Equipment Maintenance Log

This log covers scheduled and unscheduled maintenance at the Dunmore pumping station. Each line records one intervention on one asset. Status codes follow the procedure manual of the station.

Table 1. Interventions, first quarter

Job	Asset	Date	Crew	Status
J-0101	Intake pump 1	2026-01-05	Crew North	Completed
J-0102	Booster pump B	2026-01-06	Crew South	Deferred
J-0103	Standby generator	2026-01-08	Crew East	In progress
J-0104	Intake pump 2	2026-01-09	Crew North	Completed
J-0105	Chlorine dosing unit	2026-01-11	Crew South	Completed
J-0106	Control panel	2026-01-12	Crew East	Completed
J-0107	Booster pump A	2026-01-14	Crew North	Completed
J-0108	Inlet screen	2026-01-15	Crew South	Completed
J-0109	Intake pump 1	2026-01-17	Crew East	Deferred
J-0110	Booster pump B	2026-01-18	Crew North	In progress
J-0111	Standby generator	2026-01-20	Crew South	Deferred
J-0112	Intake pump 2	2026-01-21	Crew East	In progress
J-0113	Chlorine dosing unit	2026-01-23	Crew North	Completed
J-0114	Control panel	2026-01-24	Crew South	Completed
J-0115	Booster pump A	2026-01-26	Crew East	Completed
J-0116	Inlet screen	2026-01-27	Crew North	Completed
J-0117	Intake pump 1	2026-01-29	Crew South	Completed
J-0118	Booster pump B	2026-01-30	Crew East	Deferred
J-0119	Standby generator	2026-02-01	Crew North	In progress
J-0120	Intake pump 2	2026-02-02	Crew South	Completed
J-0121	Chlorine dosing unit	2026-02-04	Crew East	In progress
J-0122	Control panel	2026-02-05	Crew North	Completed
J-0123	Booster pump A	2026-02-07	Crew South	Completed
J-0124	Inlet screen	2026-02-08	Crew East	Completed
J-0125	Intake pump 1	2026-02-10	Crew North	Deferred
J-0126	Booster pump B	2026-02-11	Crew South	Completed
J-0127	Standby generator	2026-02-13	Crew East	Deferred
J-0128	Intake pump 2	2026-02-14	Crew North	In progress
J-0129	Chlorine dosing unit	2026-02-16	Crew South	Completed
J-0130	Control panel	2026-02-17	Crew East	Completed
J-0131	Booster pump A	2026-02-19	Crew North	Completed

Job	Asset	Date	Crew	Status
J-0132	Inlet screen	2026-02-20	Crew South	Completed
J-0133	Intake pump 1	2026-02-22	Crew East	Completed
J-0134	Booster pump B	2026-02-23	Crew North	Deferred
J-0135	Standby generator	2026-02-25	Crew South	In progress
J-0136	Intake pump 2	2026-02-26	Crew East	Deferred
J-0137	Chlorine dosing unit	2026-02-28	Crew North	In progress
J-0138	Control panel	2026-03-01	Crew South	Completed
J-0139	Booster pump A	2026-03-03	Crew East	Completed
J-0140	Inlet screen	2026-03-04	Crew North	Completed
J-0141	Intake pump 1	2026-03-06	Crew South	Completed
J-0142	Booster pump B	2026-03-07	Crew East	Completed
J-0143	Standby generator	2026-03-09	Crew North	Deferred
J-0144	Intake pump 2	2026-03-10	Crew South	In progress
J-0145	Chlorine dosing unit	2026-03-12	Crew East	Completed
J-0146	Control panel	2026-03-13	Crew North	In progress
J-0147	Booster pump A	2026-03-15	Crew South	Completed
J-0148	Inlet screen	2026-03-16	Crew East	Completed
J-0149	Intake pump 1	2026-03-18	Crew North	Completed
J-0150	Booster pump B	2026-03-19	Crew South	Deferred
J-0151	Standby generator	2026-03-21	Crew East	Completed
J-0152	Intake pump 2	2026-03-22	Crew North	Deferred
J-0153	Chlorine dosing unit	2026-03-24	Crew South	In progress
J-0154	Control panel	2026-03-25	Crew East	Completed
J-0155	Booster pump A	2026-03-27	Crew North	Completed
J-0156	Inlet screen	2026-03-28	Crew South	Completed

Summary

Most interventions were completed on the day they were opened. Deferred jobs are carried over to the April schedule. The standby generator will be replaced in the second half of the year.