



## Site Visit

### General information

Date	2024-08-14
Time-in	10:15 (-7 GMT)
Field crew members	DB, MT, KP
Station code	Kuzkwa River-01FW001-ST
Enter station name	
Site conditions	Water level lower than previous visit. No signs of tampering.
Photo of site upon arrival	A photograph showing a river with clear, brownish water flowing through a forested area. A large rock is visible in the water. The water is shallow near the shore, where some aquatic plants are growing. The background shows a dense forest of evergreen trees.

### Objectives

Is this a new site?	No
Is this a weather station?	No
Is this a telemetry visit?	



## Site Visit

Are data being downloaded?	Yes
Are equipment being deployed?	Yes
Are equipment being retrieved?	Yes

## Subforms

### Data download

#### General information

Equipment code for logger	NHG017
Are you re-deploying a water temperature logger?	Yes
Did you successfully pull the data?	Yes
Enter the file name	01FW001_Kuzkwa_21481630_20240814
Comments	NA

### Data details

Are there any issues with the data?	No
Data description	

### Water Temperature Redeployment

Latitude	54797317
Longitude	124692945
Elevation	752
Comments	

### Deployed equipment

#### Deployment information

Is this a logger?	Yes
Is this a replacement WTMP logger?	Yes
Equipment code - logger	NHG0308
Equipment code - sensor	
Height/Depth	40.0cm
Logging interval	15minutes
Logging start date	2024-08-14
Logging start time	11:00 (-7 GMT)



Date Submitted: 2024-08-14 11:37  
Submitted By: dylan.broeke@unbc.ca

## Site Visit

Deployment photo





Date Submitted: 2024-08-14 11:37  
Submitted By: dylan.broeke@unbc.ca

## Site Visit





## Site Visit



Comments if needed	NA
--------------------	----

## WTMP Replacement

Latitude	54797317
Longitude	124692945
Elevation	752
Comments	

## Retrieved equipment

### Deployment information

Is this a logger?	Yes
Equipment code - logger	NHG0017



## Site Visit

Equipment code - sensor	
Photo	
Reason for retrieval	Replaced with new logger
Comments	

## Future Tasks

Are future tasks required?	Yes
List of future tasks	Replace orange lid next visit.

## Closing information

Comments, if needed	
Photos	
Time-out	10:30 (-7 GMT)