PT NIRWANA BHUMI ENERGY	WORKPLACE INSPECTION CHECKLIST AND CORRECTIVE ACTION REQUEST FORM	Form No: 0013-FOR-HSE-COO-X-2026 Revision: 0 Date: October 2026
Standard Operational Reference: 0007-SOP-HSE-CEO-X-2026		

Project / Facility:	PT NBE Main Yard & Operating Site	**Inspection Date:**	October 2026
Lead Inspector:	HSE Officer & Area Supervisor	**CAR Priority Level:**	Priority 1 / 2 / 3

No	Inspection Item / Hazard Observed	Defect Category	Corrective Action Required (CAR)	Due Date / PIC
1	Damaged insulation on portable welding lead cable	Electrical Safety	Tag out cable immediately and replace lead wire	< 24 Hrs / Tech
2	Missing cylinder safety cap on stored oxygen bottle	Pressurized Gas	Fit valve protection cap and secure with chain	< 24 Hrs / Yard Lead
3	Obstructed access to APAR 12kg DCP at Warehouse	Fire Protection	Clear pallets to maintain 1-meter clear clearance	Immediate / PIC
4	Trip hazard from loose hoses across pedestrian walkway	Housekeeping	Reroute hoses using overhead cable bridges	< 48 Hrs / Supv
5	Scaffolding tag missing green inspection status	Work at Height	Inspect structure and install current green Scafftag	< 24 Hrs / Scaffolder

Field Inspector (HSE):	Area Superintendent / PIC:	Close-Out Verification (CTO):
Signature: Date: October 2026	Signature: Date: October 2026	Signature: Date: October 2026