SAMPLE



MAMO TRANSPORTATION, INC. P.O. Box 40 Osceola, IN 46561 USDOT # 753560

P/U

Bill of Lading
This document is subject to all terms and conditions of bill-of-lading and common law. Settlement Fax: 866-450-3580 Phone: 888-668-6885 IN X 7802 ARX 2990 NCX 4902 PAX 7804 Safety X 7803 Safety Fax 888-466-9110

> Start Miles 42 Total Miles 2400

www.mamouransportation.com	A-1000000000000000000000000000000000000			
Contract Driver: Joseph Dr	iver	ID#05IN9999 Load# 78910		
Unit #: 123456		5596 7 Trailer VIN#		
Shipper/Origin ABC Company 100 Main Stre Salt Lake City Phone: 800-564-949	et UTah 2	Consignee/Destination 123 Firm 642 Meple Lane Boston, MA Phone 800-304-4000		
Fuel Type: Diesel Gas	Empty	Vehicle 100 Kenworth Tractor Odometer		

Pre-Trip Inspection CFR 396.11	Is condition good? Yes No	Post-Trip Inspection CFR 396.11	Is condition good? Yes No
Service brakes/ parking brakes Steering Mechanism	-	Service brakes/ parking brakes Steering Mechanism	$\neq =$
Lights/ Reflectors/Signals Tires/ Inflation/ Condition	× =	Lights/ Reflectors/Signals Tires/ Inflation/ Condition	$\neq =$
Horn(s) Windshield Wipers/ Solvent	- =	Horn(s) Windshield Wipers/ Solvent	-
Oil Level / Belts Rear Vision Mirrors	-	Oil Level / Belts Rear Vision Mirrors	= =
Wheels / Rims / Mud flaps Coupling Devices (if applicable)	NIA -	Wheels / Rims/ Mud Flaps Coupling Devices (if applicable)	MA =
Body Condition/ Damage Safety Equipment/ Fire Extinguisher		Body Condition/ Damage Safety Equipment/ Fire Extinguisher	Z =
Cleanliness		Cleanliness	

Size <u>W/O 5/exper</u> Weight <u>27,000 6VW</u>



Shipper and driver confirm that the condition of vehicle at pick-up and release to driver is satisfactory except as noted on the pre-trip diagram and/or for hidden

damage which	h may not be appa	rent in pre-imp inspection.	
Shipper:	9BC-6	1 geln m	arlen
Date	12-12		
Driver: C	med	Driver	

Receiver has received this vehicle in good condition; acknowledges no driver/transit damage to the vehicle; and releases Mamo Transportation. Inc. except as noted in the post trip inspection diagrams.

Receiver:	123	by	Mar	tus)	Low
Date:	12-	Ne a:	5		
Driver: _	~	seph	Du	in_	