## **GOLDER WRENCH CAR CARE OPC**

9002 PUROK 1, PARULAN, PLARIDEL BULACAN 0920-904-3869 rapideplaridel@gmail.com 650-772-372-00000



**Engine No.:** 

**Chasis No.:** 

Mileage: 36,683

Next PMS: 53.683

## **REPAIR ESTIMATE FORM**

Date: 01/04/2025 Plate No: CAO9657
Customer: Louie Castro Car Make: TOYOTA
Company: Model: WIGO
Address: Balagtas Bulacan YEAR: 2019

Mobile No.: 09178833377 Engine Size: S Est. Time:

VIN: TRANS(M/A): AT/GAS Inspected By: Jericho Roxas

## PLEASE READ:

Under MAP Uniform Inspection Guidelines. We are required to document all our findings on your vehicle. This is your estimate. Our Store Manager should bring you to your car, show you the needed repairs and go over the estimate with you. Item by item. All your questions should be answered. We want you to know all your opinions. This is your car. We just want to help you keep it in good running condition.

## **MAIN CONCERNS**

Qty	Unit	Labor, Parts & Materials Description	Unit Price	Total Amount
1	1	[S] Change oil semi synthetic (Valvoline 4L)	3,500.00	3,500.00
1	1	[P] Brake Pads	800.00	800.00
			-	-
			TOTAL:	4,300.00

By signing this Repair Estimate Form, the customer acknowledges that the Store Manager has brought him/her to his/her vehicleand clearly showed and explained all the services/repair that are required and suggested services, parts & laboris on three (3) months warranty after the date service.

Prepared by: Conforme by:

Jericho Roxas Louie Castro

Estimator Customer signature over printed name

Technician(s): Quality Check By:

Ivan Jay DomingoIvan Jay DomingoTechnicianSenior Technician

John Dareil Albios Technician

Page: 1 of 1