GOLDER WRENCH CAR CARE OPC

9002 PUROK 1, PARULAN, PLARIDEL BULACAN 0920-904-3869 rapideplaridel@gmail.com 650-772-372-00000



REPAIR ESTIMATE FORM

Date: 01/17/2025Plate No: NDU12341Engine No.: 1234Customer: Marxis CaberoCar Make: ToyotaChasis No.: 1234Company: MIMSModel: Vios 1.3EMileage: 3

Address: Antipolo City

Mobile No.: 09950929709

YEAR: 2015

Engine Size: Medium

Next PMS: 20003

Est. Time:

VIN: 1234 TRANS(M/A): Manual Inspected By: Captain America

PLEASE READ:

Under MAP Uniform Inspection Guidelines. We are required to document all our findings on your vehicle. This is your estimate. Our Store Manager should bring you to your car, show you the needed repairs and go over the estimate with you.ltem by item. All your questions should be answered. We want you to know all your opinions. This is your car. We just want to help you keep it in good running condition.

MAIN CONCERNS

Qty	Unit	Labor, Parts & Materials Description	Unit Price	Total Amount
2		[P] AC Delco Oil Filter	4,000.00	8,000.00
1		[P] Display1	1,500.00	1,500.00
-	-	[S] Replace Transmission Filter1	2,500.00	2,500.00
			TOTAL:	12,000.00

By signing this Repair Estimate Form, the customer acknowledges that the Store Manager has brought him/her to his/her vehicleand clearly showed and explained all the services/repair that are required and suggested services, parts & laboris on three (3) months warranty after the date service.

Prepared by: Conforme by:

Tony Stark Marxis Cabero

Estimator Customer signature over printed name

Technician(s):

Sixram Studio Validator Test
Super Administrator Administrator

Approved By:

Hulk Logan Supervisor