



Monkey Nut, LLC.

4221-A Joe Street
Charlotte, NC 28206
704.598.6219
parts@monkeynutvw.com

Invoice

Date	Invoice #
5/23/2018	MN-6532

Bill To

Matthew Greenwald
80 Haven Ave Apt 1C
New York City, NY 10032

Ship To

Item	Description	Qty	U/M	Rate	Amount
211853619	VW EMBLEM CLIP, mounts 211853601E to Bus, 3 required per car, 1973-1979 Bus, each	3		0.00	0.00T
111837361	FELT CHANNEL CLIP, secures felt channel to door, 1965-1977 Bug (non-convertible Beetles), 1968-1979 Bus, 10 required per car, each	10		2.65	26.50T
211843800	SLIDING DOOR TRACK COVER SEAL, black beading that seals sliding door track cover to body of car. Each	2		11.25	22.50T
211953141TR	TURN SIGNAL LENS, front turn indicator, 1973-1979 Bus, fits left and right	2		23.85	47.70T
OSRAM194	Side marker bulb, no base, OSRAM	2		3.50	7.00T
N177172	Bulb, running light bulb, headlights	2		1.50	3.00T
823947105b	Interior overhead light lens	1		10.00	10.00T
211598201	CV joint boot, IRS Thing 73-74, Bus 68-91, Vanagon 80-91, EMPI	2		8.63	17.26T
090507215	Auto Transmission Final Drive Gasket, for pan in differential/final drive housing. Should be replaced when you replace the gear oil (or if leaking). From OE Supplier.	1		36.00	36.00T
Motor oil, Brad ...	Brad Penn Motor Oil, 20/50 W	4		9.00	36.00T
021115351A	Man Oil Filter, Type 4	1		7.26	7.26T
Bos 0332019150	Bosch Relay , horn/fuel pump/blower fan, 12 V	1		12.95	12.95T
Misc Item	mail set of keys	1		10.00	10.00T
Misc Item	fuel	1		20.00	20.00T
Paint and Body	Body work and paint for vehicle components - drivers door	1		150.00	150.00T
2017 Labor Rate	- install L door, install trim, window, vent, etc - driver door assembly - install F door seals- replace jalousie window to body seals - install R jalousie window	4.5		90.00	405.00T

Subtotal

Sales Tax (7.25%)

Total

Payments/Credits

Balance Due



Monkey Nut, LLC.

4221-A Joe Street
Charlotte, NC 28206
704.598.6219
parts@monkeynutvw.com

Invoice

Date	Invoice #
5/23/2018	MN-6532

Bill To

Matthew Greenwald
80 Haven Ave Apt 1C
New York City, NY 10032

Ship To

Item	Description	Qty	U/M	Rate	Amount
2017 Labor Rate	- fit repair piece - trim, fit, clamp, weld repair piece - cut sill corner from donor - contour sill - weld and grind side window ledge - cut sill corner from donor - sand and paint window frame - sand jalousie sill - clean body work debris from interior	5		45.00	225.00T
2017 Labor Rate	- fix running lights - replace marker light bulb and front marker light bulbs and lenses - rewire license light - reinstall front emblem - correct tag light / R tail light wiring - clean rear side running light contacts - install L jalousie - install interior panels / handles etc - install dome light - interior wipe down	5		90.00	450.00T
Detail Vehicle	Full Exterior Detail of car, Includes paint touch up, clay bar, light color sand, buff and wax	1		400.00	400.00T
2017 Labor Rate	- oil change - torque heads - adjust valves - replace valve cover gaskets - reseal final drive sump plate	2		90.00	180.00T
2017 Labor Rate	- remove header - anneal exhaust gaskets - weld up header and reinstall - make up missing exhaust hanger - replaced triangle gaskets at 2 exhaust flanges	3		0.00	0.00T

Subtotal

Sales Tax (7.25%)

Total

Payments/Credits

Balance Due



Monkey Nut, LLC.

4221-A Joe Street
Charlotte, NC 28206
704.598.6219
parts@monkeynutvw.com

Invoice

Date	Invoice #
5/23/2018	MN-6532

Bill To

Matthew Greenwald
80 Haven Ave Apt 1C
New York City, NY 10032

Ship To

Item	Description	Qty	U/M	Rate	Amount
2017 Labor Rate	- R&R driver side axle - clean, repack, and install new boots (old ones were both torn. passenger side axle was fine) - installed blower fan relay and wired - test OK	1.5		90.00	135.00T

Subtotal	\$2,201.17
Sales Tax (7.25%)	\$159.58
Total	\$2,360.75
Payments/Credits	-\$394.89
Balance Due	\$1,965.86