



Monkey Nut, LLC.

4221-A Joe Street
Charlotte, NC 28206
704.598.6219
parts@monkeynutvw.com

Invoice

| Date | Invoice # |
|-----------|-----------|
| 2/27/2018 | MN-6481 |

Bill To

Matthew Greenwald
80 Haven Ave Apt 1C
New York City, NY 10032

Ship To

| Item | Description | Qty | U/M | Rate | Amount |
|-----------------|---|-----|-----|--------|---------|
| 211843800 | SLIDING DOOR TRACK COVER SEAL, black beading that seals sliding door track cover to body of car. Each | 2 | | 11.25 | 22.50T |
| 241837601 | Complete Vent Window Assembly, with glass and seal installed, Bus 68-79, new, left | 1 | | 326.24 | 326.24T |
| 241837602 | Complete Vent Window Assembly, with glass and seal installed, Bus 68-79, new, right | 1 | | 326.24 | 326.24T |
| 211853322GR | OUTSIDE SCRAPER, includes rubber and aluminum trim, 1968-1979 Bus right, made in Germany | 1 | | 63.70 | 63.70T |
| 211853321GR | OUTSIDE SCRAPER, includes rubber and aluminum trim, 1968-1979 Bus left, made in Germany | 1 | | 62.40 | 62.40T |
| 2017 Labor Rate | - remove side rails, wash/clean rails, install beading - clean and paint sliding door swing mech and latch - remove front door panels | 1 | | 90.00 | 90.00T |
| 2017 Labor Rate | - remove front door windows, regulators, scrapers, etc - remove jalousie windows - wire wheel sills, prime - cut out window sill and prep opening for repair panel | 4 | | 90.00 | 360.00T |
| 2017 Labor Rate | - weld repair and finish driver door cracks - install R window trim / regulator / vent / etc - cut and prep donor sill - clean/lubricate/ reassemble / install sliding door - remove drivers door to repaint upper half where repairs were made | 5 | | 90.00 | 450.00T |

| | |
|--------------------------|------------|
| Subtotal | \$1,701.08 |
| Sales Tax (7.25%) | \$123.33 |
| Total | \$1,824.41 |
| Payments/Credits | -\$69.97 |
| Balance Due | \$1,754.44 |