

Order Details

Car Health Card

Name	Mayank Dwivedi	Brand	Hyundai
Date	2022-07-27	Model	Venue
Invoice Number	20220717938043845	Registration No.	UP78GB2462
Odometer Rd	60655	Fuel Type	Diesel
Order Remark	vehicle at workshop work in progress	City	Bhopal
Address	Sanchi ,Fpmr+92Q, Sanchi, Madhya Pradesh 464661, India		

Detailed Car Info

Registration Date	NA	Engine Number	NA
Vehicle Class	Private Car	Chassis Number	NA
Registration Location	NA	Insurance Expiration	NA

30% INCREASE IN RESALE VALUE OF YOUR CAR

CAR HEALTH CARD





OUR PARTNERS









Systems	Good	Moderate	Critical
---------	------	----------	----------

Heating & AC		-	-
GoMechanic Expert Analysis <ul style="list-style-type: none">• The AC Air Flow is optimum.• The AC Airflow is at optimum temperature.• No noises observed from the AC Blower.			

Schedule Maintenance		-	-
GoMechanic Expert Analysis <ul style="list-style-type: none">• Engine Oil level is optimum.• Oil Filter is in a good condition.• Air Filter Element is clean.• Coolant level is optimum.• AC Filter Element is clean.• The "Service Due" warning light is off.			

Exterior & Interior (Body & Accessories)	-		-
GoMechanic Expert Analysis <ul style="list-style-type: none">• Our Experts recommend 3M Car Rubbing & Polishing and Deep All Round Spa at the earliest.			

Brakes & Wheels		-	-
GoMechanic Expert Analysis <ul style="list-style-type: none">• Front Brake Pads/Discs are in good condition.• The Brake Fluid Level is optimum.• No unusual noise observed from the Brakes.• Braking Efficiency is as desired.• No Brake Warning/ABS light detected.			

Engine		-	-
GoMechanic Expert Analysis <ul style="list-style-type: none">• The "Check Engine" warning light is off.• No Engine Noise/Vibrations observed.• No abnormal Smoke observed.• The Engine Temperature is normal.• No Leakage of fluids is observed.• No unusual noise observed from the Drive Belt.			

Clutch & Transmission		-	-
-----------------------	---	---	---

GoMechanic Expert Analysis			
-----------------------------------	--	--	--

- No Clutch Noise/Vibrations detected.
- Gear Shifting is Smooth and Slick.
- No Transmission/Drivetrain light detected.
- The Clutch Pedal is working normally.
- No Oil Leakage detected from underneath the car.

Electrical



-

-

GoMechanic Expert Analysis

- No Wiring Harness/Module damage was observed.
- The Speakers and Stereo systems are working perfectly.

Suspension & Steering



-

-

GoMechanic Expert Analysis

- Front Suspension found to be in Good Condition
- No Problems found in Rear Suspension System
- All Wheels hubs are in good condition
- No Noise is detected from drive axle.

