



## Outside “Corner Shots”

Corner shots should appear as if in a virtual parking space. No portion of the vehicle should be obscured by other objects, sun or shadow.

### Examples of good corner shots



## Examples of Bad corner shots

4:29:12 PM 9/26/2017



These photos should fail because portions of the vehicle are out of view or not visible due to excessive glare or shadow.



## VIN or Manufacturer Plate



The entire manufacturer plate should be in view and readable.



## Example of Bad VIN photo



This photo should fail because the VIN is out of focus and unreadable.

## Odometer “Mileage”



The mileage should be in view and readable.



Some vehicles have electrical issues due to flooding and will not display a mileage. Alternate photos are acceptable for flood vehicles.

Mileage photos should only be “Failed” for flood vehicles if the odometer is clearly available but not readable.

## Interior Front “Dash”



Interior front photos should display the dash and front seats. Photos should be clear of trash, although a small amount that does not obscure the image is acceptable.



This photo should fail due to excessive trash in the vehicle.



## Interior Rear



Interior rear photos should show the backseat or truck bed. Photos should be clear of trash and vehicle body parts.

4:09:26 PM 9/26/2017



A small amount of trash that does not obscure the image is acceptable.



This photo should fail due to excessive trash in the vehicle.

## Engine



Engine photos should display the entire engine compartment.




This photo should fail due to excessive blur and a portion of the engine compartment being cut off.

## Damage



Damage photos for flood vehicles may appear as an exterior photo or close up of damage if any exists. Unlike the corner shots, the full vehicle does not need to be in view.

 **Detailing Services**

THE FOLLOWING SERVICES WERE PERFORMED ON THIS VEHICLE

- ✓ Cleaned & Washed Engine Compartments
- ✓ Washed Interior & Exterior
- ✓ Detailed Interior
- ✓ Extracted Water & Added Mildew Packet
- ✓ Personal Items Bagged
- ✓ Silicone Engine
- ✓ WD40 Fuse Box, Seat Rails, Door & Trunk Hinges

Notwithstanding the above description of services performed on this vehicle, IAA makes no representations or warranties of any kind, including but not limited to, the condition, merchantability or fitness for a particular purpose of this or any other vehicle sold through its auction, online or otherwise. This vehicle, and its condition, is sold as-is, with all faults. IAAI is not responsible for any damage to the vehicle or its contents. IAAI is not responsible for any loss of data or information. IAAI is not responsible for any damage to the vehicle or its contents. IAAI is not responsible for any loss of data or information. IAAI is not responsible for any damage to the vehicle or its contents. IAAI is not responsible for any loss of data or information.

000-20593169 - 09/25/2017 INSURANCE AUTO AUCTIONS, INC. © - IAAI.COM

Damage photos may also be replaced with an image listing flood cleanup services.

Damage photos should only be failed if personally identifiable information is present such as a license plate or the image does not represent the vehicle or services such as a photo of the ground or sky.