

Property Condition Report
Apartment — Condition Assessment

Creek View Tower Unit 527
Dubai Creek Harbour, Dubai



09 Jul 2026, 06:34 PM

PROPERTY DETAILS

TYPE	Apartment	AREA	Dubai Creek Harbour	CITY	Dubai
BUILDING	Creek View Tower	UNIT	527	MAKANI	75385
AREA (SQFT)	900	BEDS	1	BATHS	1
FURNISHED	No				

LANDLORD

Name: John Walter
Phone: +971 546784519
Email: Johnwalter@johnwalter.ae

TENANT

Name: Linda Gold
Phone: +971 513797846
Email: lindagold@goldlinda.ae

INSPECTION SUMMARY

8
ROOMS

59/115
ITEMS

36
GOOD

9
ISSUES

TENANCY DETAILS

LEASE START	01 Jul 2026
LEASE END	30 Jun 2027
CONTRACT	HSUI-1762

Disclaimer / إخلاء المسؤولية

English

This Property Condition Report ("Report") has been prepared using the Meinspect application ("the Application") for informational and documentation purposes only. The Report is intended to provide a general assessment of the property condition at the time of inspection.

العربية

تم إعداد تقرير حالة العقار ("التقرير") باستخدام تطبيق Meinspect ("التطبيق") لأغراض توثيقية وتوثيقية فقط. يهدف التقرير إلى تقديم تقييم عام لحالة العقار في وقت الفحص.

 Entrance / Foyer Assessment

 Entrance / Foyer

General Good

Brown Wooden door

Light Fixtures Good

LED

Tile / Marble Condition Poor

Old

Grout Lines Poor

Visible marks everywhere

Living Room Assessment

Living Room

General Fair

Big size

Paint Condition Good

New

Holes / Marks Fair

Marks are visible

Light Fixtures Good

2 chandeliers with 5 LEDs each

Tile / Marble Condition Fair

Fair condition

Carpet Condition Good

Good

Grout Lines Poor

Deep and uneven

Glass Condition Fair

Clear

Window Frames Good

Sturdy

Handles / Latches Poor

Broken

Light Switches Fair

Basic switches

Power Sockets Poor

Very old

AC Vents Fair

Clean

Thermostat Good

Honeywell Thermostat

Kitchen Assessment

Kitchen

General Good

Good size

Countertop Very Good

Gas bases

Cabinets / Drawers Good

Ample storage

Sink / Faucet Good

Double Sink

Stove / Oven Good

Westpoint Oven working

Extractor Hood Good

Working

Refrigerator Good

Midea

Holes / Marks Poor

Lots of marks

Tile / Marble Condition Good

Clean

Light Switches Fair

Old

Power Sockets Good

Good

Light Fixtures Good

2 panels

Balcony Assessment

Balcony

General Good
Decent

Flooring Good
Good

Railing / Balustrade Good
Good

Drainage Fair
Small

Walls / Ceiling Good
Clean

Master Bedroom Assessment

Master Bedroom

General Good

Well planned

Paint Condition Good

Good

Light Fixtures Good

Ample light

Tile / Marble Condition Poor

Marks

Grout Lines Poor

Poor

Window Frames Good

Good

Handles / Latches Fair

Painted

Room Doors Good

Wooden door

Handles / Knobs Poor

Scratched

Locks / Deadbolts Good

Vista Lock and Key

Light Switches Good

Basic switches

Power Sockets Good

Ample sockets

AC Vents Good

2 vents

Bedroom 2 Assessment

Bedroom 2

General Not Rated

Paint Condition Not Rated

Wall Cracks Not Rated

Holes / Marks Not Rated

Moisture / Dampness Not Rated

Wallpaper / Wall Covering Not Rated

Paint Condition Not Rated

Cracks Not Rated

Water Stains / Leaks Not Rated

Light Fixtures Not Rated

Ceiling Fan Not Rated

Tile / Marble Condition Not Rated

Carpet Condition Not Rated

Grout Lines Not Rated

Scratches / Stains Not Rated

Level / Evenness Not Rated

Glass Condition Not Rated

Window Frames Not Rated

Handles / Latches Not Rated

Seals / Gaskets Not Rated

Room Doors Not Rated

Door Frames Not Rated

Handles / Knobs Not Rated

Locks / Deadbolts Not Rated

Light Switches Not Rated

Power Sockets Not Rated

 Master Bathroom Assessment

 Master Bathroom

General Good
Good

Toilet Fair
Old

Sink / Vanity Fair
Marks

Bathtub / Shower Fair
Old tub

Faucets / Taps Fair
Mixer with handshower

Tiles / Grout Good
Clean tiles

Exhaust Fan Good
New fan

Towel Rails Good
Good

Tile / Marble Condition Fair
Old with marks

Light Switches Good
Outside

Light Fixtures Good
1 light

 Bathroom 2 Assessment

 Bathroom 2

General Not Rated

Toilet Not Rated

Sink / Vanity Not Rated

Bathtub / Shower Not Rated

Faucets / Taps Not Rated

Tiles / Grout Not Rated

Exhaust Fan Not Rated

Mirror Not Rated

Towel Rails Not Rated

Paint Condition Not Rated

Wall Cracks Not Rated

Holes / Marks Not Rated

Tile / Marble Condition Not Rated

Carpet Condition Not Rated

Grout Lines Not Rated

Water Pressure Not Rated

Hot Water Not Rated

Drainage Not Rated

Light Switches Not Rated

Power Sockets Not Rated

Light Fixtures Not Rated

Digital Signatures & Legal Declaration

TENANT



Linda Gold

LANDLORD



John Walter

INSPECTOR



Inspector