

Wed, 02 September 2026

STATE OF TEXAS §

This is to certify that I, Jim Markham, am employed by the Texas Department of Transportation (Department); that I am the Custodian of Motor Vehicle Crash Records for such Department; that the attached is a true and correct copy of the peace officer's report filed with the Department referred to in the attached request with the crash date of Fri, 28 August 2026, which occurred in Tarrant County; that the investigations of motor vehicle crashes by peace officers are authorized by law; that this Texas Peace Officer's Crash Report is required by law to be completed and filed with this Department; that this report sets forth matters observed pursuant to duty imposed by law as to which matters there was a duty to report, or factual findings resulting from an investigation made pursuant to authority granted by law.



Jim Markham
Director, Crash Data & Analysis Section
Traffic Safety Division
125 East 11th Street
Austin, TX 78701-2483





Law Enforcement and
TxDOT use Only

Texas Peace Officer's Crash Report
(Form CR-4 01/01/2026)
Questions? Call 844/274-7457

TxDOT Crash ID:	21609720.1
Case ID:	2600037671
Page:	1 of 3

Crash and Location Information																
Crash Date	Crash Time	Report Date	Total Units	Total Persons	Fatal	CMV	School Bus	Railroad	MAB	Supplement	Active School Zone					
08/28/2026	05:00	08/28/2026	2	2	NO	NO	NO	NO	NO	NO	NO					
County Name	City Name	Outside City Limits			Latitude		Longitude		\$1000 Damage to Property							
TARRANT	GRAPEVINE	NO			32.95514411		-97.03802577		YES							
Road on Which Crash Occurred																
Roadway System	Highway	Roadway Part	Block	Street Prefix	Street Name				Street Suffix							
STATE HIGHWAY	121	SERVICE/ FRONTAGE ROAD	1800		SH 121											
Street Description			Speed Limit	Direction of Traffic	Toll Road / Toll Lane	Const. Zone	Workers Present	Private Drive or Road, Private Property or Parking Lot		Secondary Crash	At Intersection					
			65	NORTH	NO	NO	NO	NO		NO	YES					
Intersecting Road																
Roadway System	Highway	Roadway Part	Block	Street Prefix	Street Name				Street Suffix							
LOCAL ROAD/STREET		MAIN/PROPER LANE	2700		Bass Pro				DRIVE							
Speed Limit	Street Description									Railroad Crossing #						
45																
Environmental and Roadway Conditions																
Weather Condition		Light Condition		Entering Roads			Roadway Type									
CLEAR		DARK, LIGHTED		THREE ENTERING ROADS - T			TWO-WAY, DIVIDED, PROTECTED MEDIAN									
Roadway Alignment			Surface Condition				Traffic Control									
STRAIGHT, GRADE			DRY				SIGNAL LIGHT									
Investigator Information																
Investigator Name				ID				Local Use								
Smith, R				14177												
Agency						ORI		Service/Region/DA		Investigation Complete						
GRAPEVINE POLICE DEPARTMENT						TX2201300		01/ /		YES						
How Notified			Date Notified	Time Notified	Date Arrived	Time Arrived	Date Roadway Cleared	Time Roadway Cleared	Date Scene Cleared	Time Scene Cleared						
Dispatch			08/28/2026	05:02	08/28/2026	05:05	08/28/2026	05:53	08/28/2026	05:53						
Crash Diagram – Not to Scale																
1700 (N) S.H. 121 (N/B Service Rd) 2800 Bass Prounit 1 Unit 1 Unit 2 Unit 2 2900 Bethal Rd. 100 (N) S.H. 121 (N/B Service Rd)																

Copy from Custodial File



Law Enforcement and
TxDOT use Only

Texas Peace Officer's Crash Report
(Form CR-4 01/01/2026)
Questions? Call 844/274-7457

TxDOT Crash ID:	21609720.1
Case ID:	2600037671
Page:	2 of 3

Investigator Narrative												
Unit 1 Failed to yield right of way while turning left on a flashing yellow light. Unit 1 entered the intersection striking unit 2 causing damage to both vehicles.												
Unit Information												
Unit #1												
Unit Description	Parked Vehicle	Hit and Run	Autonomous Unit	Autonomous Level Engaged	Responder Struck	Police, Fire, EMS on Emergency	Vehicle Inventoried					
MOTOR VEHICLE	NO	NO	NO	NO AUTOMATION	NO	NO	NO					
In Tow	By Unit #	License Plate State	License Plate Num.	VIN	Vehicle Year	Vehicle Color						
NO		TEXAS	WHB6147	1V2DR2CA0SC529343	2025	SILVER						
Vehicle Make		Vehicle Model			Vehicle Body Style							
VOLKSWAGEN		ATLAS			SPORT UTILITY VEHICLE							
Proof of Financial Responsibility		Financial Responsibility Type		Financial Responsibility Name								
YES		LIABILITY INSURANCE POLICY		PROGRESSIVE (COUNTY MUTUAL) INS. CO.								
Financial Responsibility Number				Financial Responsibility Phone Number								
936659747				(800) 776-4737								
Owner/Lessee		Owner/Lessee Name		Owner/Lessee Address								
OWNER		Dashora, Melody, Dawn		6058 Midnight Moon DR Frisco, TX 75036								
Vehicle Damage Direction of Force		Vehicle Damage Description					Vehicle Damage Severity					
3 O'CLOCK		RIGHT FRONT QUARTER DAMAGE ANGULAR IMPACT					DAMAGED 4					
Towed By				Towed To								
B&B WRECKER (817) 283-2121				1201 W EULESS BLVD. EULESS, TX 76040								
Unit Contributing Factors and Defects												
Contributing Factor (Investigator's Opinion)		Factor Description										
1		FAILED TO YIELD RIGHT OF WAY - TURNING LEFT										
2		TURNED WHEN UNSAFE										
Primary Person in Unit #1												
Person #	Person Type			Seat Position								
1	DRIVER			FRONT LEFT OR MOTORCYCLE DRIVER								
Name: Last, First, Middle						Date of Birth						
Dashora, Melody, Dawn						07/01/1978						
Address (Street, City, State, Zip)												
6058 Midnight Moon DR Frisco, TX 75036												
DL/ID Type		DL/ID State		DL/ID Number		DL Class						
DRIVER LICENSE		TEXAS		44807726		CLASS C						
CDL Endorsements				DL Restrictions								
NONE				NONE								
Injury Severity		Age	Ethnicity		Sex	Ejected						
SUSPECTED MINOR INJURY		48	WHITE		FEMALE	NO						
Restraint			Airbag		Helmet	Solicitation						
SHOULDER & LAP BELT			DEPLOYED, MULTIPLE		NOT APPLICABLE	NO						
Alcohol Specimen		Alcohol Result	Drug Specimen		Drug Result	Drug Category						
NONE			NONE		NOT APPLICABLE	NOT APPLICABLE						
Disposition of Killed or Injured												
Taken To			Taken By			Date of Death	Time of Death					
Baylor Grapevine			Grapevine EMS									
Unit #2												
Unit Description	Parked Vehicle	Hit and Run	Autonomous Unit	Autonomous Level Engaged	Responder Struck	Police, Fire, EMS on Emergency	Vehicle Inventoried					
MOTOR VEHICLE	NO	NO	NO	NO AUTOMATION	NO	NO	NO					
In Tow	By Unit #	License Plate State	License Plate Num.	VIN	Vehicle Year	Vehicle Color						
NO		TEXAS	vdw2544	WBAKN9C5XED681044	2014	WHITE						
Vehicle Make		Vehicle Model			Vehicle Body Style							
BMW		550			PASSENGER CAR, 4-DOOR							
Proof of Financial Responsibility		Financial Responsibility Type		Financial Responsibility Name								
NO												
Financial Responsibility Number				Financial Responsibility Phone Number								
Owner/Lessee		Owner/Lessee Name		Owner/Lessee Address								
OWNER		Savala, Tamika		801 Lake Canyon PKWY Irving, TX 75039								
Vehicle Damage Direction of Force		Vehicle Damage Description					Vehicle Damage Severity					
12 O'CLOCK		FRONT END DAMAGE DISTRIBUTED IMPACT					DAMAGED 3					
Towed By				Towed To								
B&B WRECKER (817) 283-2121				1201 W EULESS BLVD. EULESS, TX 76040								

Copy from Custodial File



Law Enforcement and
TxDOT use Only

Texas Peace Officer's Crash Report
(Form CR-4 01/01/2026)
Questions? Call 844/274-7457

TxDOT Crash ID:	21609720.1
Case ID:	2600037671
Page:	3 of 3

Primary Person in Unit #2							
Person #	Person Type			Seat Position			
1	DRIVER			FRONT LEFT OR MOTORCYCLE DRIVER			
Name: Last, First, Middle						Date of Birth	
SAVALA-FITZPATRICK, Tamika						08/28/1997	
Address (Street, City, State, Zip)							
2290 W Tarleton ST stephenville, TX 76401							
DL/ID Type		DL/ID State		DL/ID Number		DL Class	
DRIVER LICENSE		TEXAS		36470205		CLASS C	
CDL Endorsements				DL Restrictions			
NONE				WITH CORRECTIVE LENSES			
Injury Severity		Age	Ethnicity		Sex	Ejected	
SUSPECTED MINOR INJURY		29	BLACK		FEMALE	NO	
Restraint		Airbag		Helmet		Solicitation	
SHOULDER & LAP BELT		DEPLOYED, MULTIPLE		NOT APPLICABLE		NO	
Alcohol Specimen		Alcohol Result		Drug Specimen		Drug Result	
NONE				NONE		NOT APPLICABLE	
						Drug Category	
						NOT APPLICABLE	
Disposition of Killed or Injured							
Taken To		Taken By				Date of Death	Time of Death
Baylor Grapevine		Grapevine EMS					
////////////////// Witness Information //////////////////							
Witness #	Witness Name: Last, First, Middle			DL/ID State		DL/ID Number	
1	Mccall, Precious, KHERRIEL RAMECIA			TEXAS		47404130	
Witness Address (Street, City, State, Zip)							
2305 Summer Place DR Arlington, TX 76014							

Copy from Custodial File