



Engineer Number 011071

LOLER
POWER
GA1

NOTE: This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998. This form must be completed by a **competent** Person. This is not an approved or statutory form. Reports of Thorough Examinations may be produced in other formats.

NOTE: This form may be used to record the thorough examination and testing of lifting Equipment, as set out in the Safety, Health and Welfare at Work (General Application) regulations, 2007. this form was produced by the HSA to facilitate the recording of information, as per Schedule 1 Part E of these regulations. This form must be completed by a **Competent** person. This is not an approved or statutory form. Reports of Thorough Examinations may be produced in other formats

DATE: 14/10/2025 REFERENCE: DUM900163

Name and address of employer or owner for whom

Drogheda Hire & Sales | Drogheda

the thorough examination was made:
Please include a contact number and email, if possible)

Cement Road, Drogheda A92 DH50

Address where thorough examination was made:

Wellfield Road, Jamestown, Ráth Tó, Co. Contae na Mí, A85 HN28

Particulars identifying the lifting equipment:

9 TON THWAITES SWIVEL DUMPER 4X4

Type of Lifting Equipment:

DUMPER

Serial Number	SLCM20901908E5235
Machine Hours	0
Year of Manufacturer	2019

SAFE WORKING LOADS	9000KG
CONFIGURATION	As recommended by manufacturer

☐

Testing

☒

yes

Thorough Examination

Purpose of testing

12 monthly

Particulars of tests carried out:	Full inspection
Date of last Examination	16-10-2024 10:37
DATE OF TODAYS EXAMINATION	14/10/2025
LATEST DATE OF NEXT EXAMINATION	13-10-2026 10:38

	Defect which is a danger to person:		Repair, renew or alteration required to remedy this defect, (including Dates)
A			
	Defect which could become a danger to persons	Timeframe for defect becoming a danger	Repair, renew or alteration required to remedy this defect, (including Dates)
B			
	Minor Defects	Timeframe for defect becoming a danger	Repair, renew or alteration required to remedy this defect, (including Dates)
C	Front right hand light smashed	Asap	Repair

Parts not accessible for inspection:

None

Name, Address and qualifications of Competent person making the report. (print name in BLOCK CAPITALS)

Tru-Cert Limited Unit 13 C:TEK
Building, Riverside Road,
Carrickmacross County Monaghan

Inspector

Damien McHugh

Report: (Print name in BLOCK CAPITALS)

Employer

We Certify that: (tick when done)	
We have undertaken the test/thorough examination as prescribed	✓
We have identified defects which could be danger to persons	X
This test /thorough examination has been carried out by a competent person	✓

You Must: (tick to confirm you understand)	
The particulars in this report of thorough examination are correct	✓
Keep this report of thorough examination safe and available for inspection	✓
Arrange for a thorough examination or test before the latest date or as prescribed	✓

Signed:

Competent Person

Performing tests or thorough Examination

Damien mchugh

Signed:

Person receiving

report of thorough Examination

14-10-2025 10:39:00

92 Jamestown Park, Jamestown, Rathoath, Co. Meath, A85 PZ3, Ireland



14-10-2025 10:38:55



53.504181, -6.452895

53.504181, -6.452895

14-10-2025 10:39:10

92 Jamestown Park, Jamestown, Rathfriland, Co. Meath, A85P73, Ireland



53.504181, -6.452895

14-10-2025 10:39:21

92 Jamestown Park, Jamestown, Fatooth, Co. Meath, A85 PY73, Ireland

53.504181, -6.452895



46 Wellfield Road, Jamestown, Ráth Tó, Co. Contae na Mí, A85 HN28, Ireland

