


REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of Part E of Schedule 1 of the Safety, Health and Welfare at Work (General Application) Regulations 2007-2021 & The Lifting Operations and Lifting Equipment Regulations 1998 – LOLER (UK)

Date of Thorough Examination: 28/01/2026		Report #: CS147489		Colour Code: GREEN															
Name and Address of employer for whom the thorough examination was made: Kingscroft Developments Ltd, 9 Abbey House, Main St, Clonee, Co Meath		Address of premises at which the examination was made: Stillorgan Road, Foxrock, Co. Dublin																	
Description: SLING 8M Serial No: E2174920308006 Category: LIFTING ACCESSORY Manufacturer: TENSYS		Safe Working Load(s): 3000KG	Date of manufacturer if known: 04/2024	Date of last thorough examination: N/A															
Is this the first examination after installation or assembly at a new site or location? <table border="1"> <tr> <th>Yes</th> <th>No</th> </tr> <tr> <td></td> <td>✓</td> </tr> </table>		Yes	No		✓	Was the examination carried out: <table border="1"> <tr> <th>Yes</th> <th>No</th> </tr> <tr> <td>✓</td> <td></td> </tr> <tr> <td></td> <td>✓</td> </tr> <tr> <td></td> <td>✓</td> </tr> <tr> <td></td> <td>✓</td> </tr> </table> Within an interval of 6 months? Within an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?				Yes	No	✓			✓		✓		✓
Yes	No																		
	✓																		
Yes	No																		
✓																			
	✓																		
	✓																		
	✓																		
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (If none state NONE): NONE																			
Is the above a defect which is of immediate danger to persons?				YES	NO														
Is the above a defect which is not yet but could become a danger to persons (if YES state the date by when)				NONE	✓														
Particulars of any repair, renewal or alteration required to remedy the defect identified above:																			
NONE																			
Identification of any parts not accessible for examination:																			
NONE																			
Particulars of any tests carried out as part of the examination: (If none state NONE):																			
VISUAL AND LOAD TEST																			
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	NO														

Name / Signature of person making and authenticating this report with qualification: Kieran Cullivan LLOYDS BRITISH Qualification		Latest date by which next thorough examination must be carried out: 28/07/2026	
			
Name and address of employer of persons making and authenticating this report: Safe Cert (Part of the Safety Solutions Group) 2 Lyncon Court, Snugborough Business & Technology Park, Blanchardstown, Dublin, D15 NP49			