

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998 (LOLER) & Safety, Health and Welfare at Work (General Application) Regulations 2007 - SI. No. 299/2007 and The Work at Height Regulations 2005 when safety equipment is being inspected.

Date of Thorough Examination: 10/02/2025		Report #: 157197	Colour Code: None	Job No: R27874														
Name and Address of employer for whom the thorough examination was made: KILLOLA QUARRIES LTD, KILLOLA, ROSCAHILL, CO. GALWAY		Address of premises at which the examination was made: KILLOLA QUARRIES LTD, KILLOLA, ROSCAHILL, CO. GALWAY																
Description and identification of the equipment: JCB JS 160W RUBBER DUCK C/W ORIEL FULLY AUTOMATIC QUICK HITCH (S/N 002935) - JCBJW16EPJ2584129 182 L 3352		Date of manufacture if known: 2018																
Safe Working Load(s) (Kgs(Unless Otherwise Stated)) 2400KG @ 7M OUTRIGGERS DOWN 1400KG @7M OUTRIGGERS UP		Test Load Applied Kgs(Unless Otherwise Stated)																
Is this the first examination after installation or assembly at a new site or location? <table border="1" style="border-collapse: collapse; text-align: center;"> <tr> <th style="padding: 5px;">Yes</th> <th style="padding: 5px;">No</th> </tr> <tr> <td style="height: 40px;"></td> <td style="text-align: center; vertical-align: middle;">✓</td> </tr> </table>		Yes	No		✓	Was the examination carried out: PERIODIC EXAMINATION Within an interval of 6 months? Within an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances? <table border="1" style="border-collapse: collapse; text-align: center;"> <tr> <th style="padding: 5px;">Yes</th> <th style="padding: 5px;">No</th> </tr> <tr> <td style="height: 20px;"></td> <td style="text-align: center; vertical-align: middle;">✓</td> </tr> <tr> <td style="text-align: center; vertical-align: middle;">✓</td> <td style="height: 20px;"></td> </tr> <tr> <td style="height: 20px;"></td> <td style="text-align: center; vertical-align: middle;">✓</td> </tr> <tr> <td style="height: 20px;"></td> <td style="text-align: center; vertical-align: middle;">✓</td> </tr> </table>			Yes	No		✓	✓			✓		✓
Yes	No																	
	✓																	
Yes	No																	
	✓																	
✓																		
	✓																	
	✓																	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (If none state NONE): NONE																		
Is the above a defect which is of immediate danger to persons?																		
			YES	NO														
Is the above a defect which is not yet but could become a danger to persons (if YES state the date by when)																		
N/A																		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE																		
Identification of any parts not accessible for examination: NONE																		
Particulars of any tests carried out as part of the examination: (If none state NONE): VISUAL INSPECTION																		
Observations made by the engineer during the examination: (If none state NONE): NONE																		
IS THIS EQUIPMENT SAFE TO OPERATE?																		
			YES	NO														
Name / Signature of person making and authentication this report with occupation: Michael Donnellan Competent, certified inspector. All certificates available on request.		Latest date by which next thorough examination must be carried out: 10/02/2026																
<i>Michael Donnellan</i>																		
KMS Head Office Tuam Co. Galway , Phone: +353 93 26300 , office@kms.ie																		