

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998 (LOLER) & Safety, Health and Welfare at Work (General Application) Regulations 2007 - SI. No. 299/2007 and The Work at Height Regulations 2005 when safety equipment is being inspected.

Date of Thorough Examination: 10/02/2025		Report #: 157198	Colour Code: None	Job No: R27874												
Name and Address of employer for whom the thorough examination was made: KILLOLA QUARRIES LTD, KILLOLA, ROSCAHILL, CO. GALWAY		Address of premises at which the examination was made: KILLOLA QUARRIES LTD, KILLOLA, ROSCAHILL, CO. GALWAY														
Description and identification of the equipment: KOMATSU PC138US-11 EXCAVATOR C/W TEFRA FULLY AUTOMATIC QUICKHITCH - KMTPC261AKA055700		Date of manufacture if known: 2020														
Safe Working Load(s) (Kgs(Unless Otherwise Stated)) 1200KG @7.5MTRS		Test Load Applied Kgs(Unless Otherwise Stated)														
Is this the first examination after installation or assembly at a new site or location? <table border="1" style="margin-left: 10px;"> <tr> <th>Yes</th> <th>No</th> </tr> <tr> <td></td> <td style="text-align: center;">✓</td> </tr> </table>		Yes	No		✓	Was the examination carried out: PERIODIC EXAMINATION <table style="width: 100%;"> <tr> <td style="width: 80%;">Within an interval of 6 months?</td> <td style="width: 20%; text-align: center;">✓</td> </tr> <tr> <td>Within an interval of 12 months?</td> <td style="text-align: center;">✓</td> </tr> <tr> <td>In accordance with an examination scheme?</td> <td style="text-align: center;">✓</td> </tr> <tr> <td>After the occurrence of exceptional circumstances?</td> <td style="text-align: center;">✓</td> </tr> </table>			Within an interval of 6 months?	✓	Within an interval of 12 months?	✓	In accordance with an examination scheme?	✓	After the occurrence of exceptional circumstances?	✓
Yes	No															
	✓															
Within an interval of 6 months?	✓															
Within an interval of 12 months?	✓															
In accordance with an examination scheme?	✓															
After the occurrence of exceptional circumstances?	✓															
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (If none state NONE): NONE																
Is the above a defect which is of immediate danger to persons? <table style="width: 100%;"> <tr> <td style="width: 75%;"></td> <td style="width: 10%; text-align: center;">YES</td> <td style="width: 10%; text-align: center;">NO</td> <td style="width: 5%; text-align: center;">✓</td> </tr> </table>						YES	NO	✓								
	YES	NO	✓													
Is the above a defect which is not yet but could become a danger to persons (if YES state the date by when) <table style="width: 100%;"> <tr> <td style="width: 60%;">N/A</td> <td style="width: 40%;"></td> </tr> </table>					N/A											
N/A																
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE																
Identification of any parts not accessible for examination: NONE																
Particulars of any tests carried out as part of the examination: (If none state NONE): VISUAL INSPECTION																
Observations made by the engineer during the examination: (If none state NONE): NONE																
IS THIS EQUIPMENT SAFE TO OPERATE? <table style="width: 100%;"> <tr> <td style="width: 75%;"></td> <td style="width: 10%; text-align: center;">YES</td> <td style="width: 10%; text-align: center;">✓</td> <td style="width: 5%; text-align: center;">NO</td> </tr> </table>						YES	✓	NO								
	YES	✓	NO													
Name / Signature of person making and authentication this report with occupation: Michael Donnellan Competent, certified inspector. All certificates available on request.		Latest date by which next thorough examination must be carried out: 10/02/2026														
KMS Head Office Tuam Co. Galway , Phone: +353 93 26300 , office@kms.ie																