

GA 1

REPORT OF INSPECTION

Safety, Health and Welfare at Work (General Application) Regulations 2007 As Amended

Name and Address of Equipment Owner/Employer:		Site where the Inspection took place:	
SEAN GLENNON PLANT HIRE & RAHEENDUFF ATTANAGH LAOIS		RAHEENDUFF ATTANAGH LAOIS	
Cust: CQ65		Policy No: JM562580949	Report No: J94296-R005
Site: A1		Broker: HOWDEN INS (IRELAND) LTD	

Item Details

Description of Plant: Hydraulic Excavator By Kobelco No. PD04010662

Aviva Item: L005

Serial No: PD04010662

Plant ID: Unknown.

Model Type: Unknown.

Date of Manufacture:

Safe Operating Limits: N/A

Item History:

Unknown

Test Cert Details:

CE marking observed

Purpose of Inspection:

Periodic Inspection

Additional Testing Carried Out:

N/A

Additional Testing/Inspection required and the date by which it must be carried out:

N/A

Parts Inaccessible

Enclosed or restricted places

A: Part(s) with defect(s) which are or could become a danger to person(s), requiring immediate cessation of the equipment and particulars of any repair, renewal or modification required to remedy such defect(s)

None

B: Part(s) with defect(s) which are not yet, but could become a danger to person(s) and particulars of any repair, renewal or modification required and the date by which they must be carried out.

The hydraulic hose for the attachment is damaged, rectify by 27/09/2025

C. Observations/Recommendations

Play noted in the boom king pin and is recommended to be rectified

Engineer Measurement Data (Any Engineer Measurement values noted below are indicative only)

None

Advisory Notes:

This item to be operated, maintained and safety notices adhered to in accordance with manufacturer's instructions. Continued safe operation is subject to any repairs, renewals or alterations if specified. Design not checked. Report to be read in conjunction with the current Declaration of Conformity where applicable. This is not a certificate of road worthiness. Arrangements to be made to remove semi-automatic quick hitches from service where utilized

I certify that on 27/08/2025 I examined this item. This report: J94296-R005 shall not be reproduced except in full and relates exclusively to the item described in this report.

Examined By:

COSMIN IANCU

Qualification:

Engineer Surveyor to
Aviva Insurance Ireland DAC
12 Cherrywood Business Park, D18, .

Telephone:

+353 87 4738261

Signature:



Date of this Inspection:

27/08/2025

Date of Issue of Report:

27/08/2025

Date of Previous Inspection:

N/A

Next Inspection Date:

27/08/2026

