

GA3 - Report of Results of Inspections of: Work Equipment for Work at a Height

Name of person (or company) for whom the inspection was carried out:

Kingscroft Development Ltd

Address where inspection was carried out (site or other workplace):

Funchal, Stillorgan Rd, Galloping Green South, Dublin 18, Ireland
(Foxrock)

Location & Description of Equipment & any Identification Numbers / Marks	Date and Time of Inspection	Results of Inspection* including defects & locations	Details of any corrective actions taken	Details of any further action necessary	Name and position of person making inspection	Signature of person who made inspection
A frame ladders 3no.	20/01/2026	In good working order	None	None	Paul Kehoe	
A frame ladders 3no.)	20/01/2026	In good working order	None	None	Paul Kehoe	