

# GA3 - Report of Results of Inspections of: Work Equipment for Work at a Height

Name of person (or company) for whom the inspection was carried out:

Kingscroft Development Ltd

Address where inspection was carried out (site or other workplace):

Castlelea Avenue, Cooltederry, Lansdowne, Co. Laois, R32 YPK3,  
Ireland (Portarlinton)

| Location<br>& Description of<br>Equipment & any<br>Identification<br>Numbers / Marks | Date and<br>Time of<br>Inspection | Results of Inspection*<br>including defects<br>& locations | Details of any corrective<br>actions taken | Details of any further<br>action necessary | Name and<br>position of<br>person<br>making<br>inspection | Signature of<br>person who<br>made<br>inspection                                    |
|--------------------------------------------------------------------------------------|-----------------------------------|------------------------------------------------------------|--------------------------------------------|--------------------------------------------|-----------------------------------------------------------|-------------------------------------------------------------------------------------|
| 3nr Aframe metal<br>ladders                                                          | 27/02/2026                        | Good                                                       | None                                       | None                                       | Colm O'Brien                                              |  |