



GA3 - Report of Results of Inspections of: Work Equipment for Work at a Height

Name of person (or company) for whom the inspection was carried out:

Kingscroft Development Ltd

Address where inspection was carried out (site or other workplace):

Wellfield Avenue, Jamestown, Ráth Tó, Co. Contae na Mí, Ireland
(Ratoath)

Location & Description of Equipment & any Identification Numbers / Marks	Date and Time of Inspection	Results of Inspection* including defects & locations	Details of any corrective actions taken	Details of any further action necessary	Name and position of person making inspection	Signature of person who made inspection
Ladder1	04/06/2025	Ok	No	No	Nigel Kelly Plumbing & Heating	
Ladder 2	04/06/2025	Ok	Na	Na	Nigel Kelly Plumbing & Heating	
Ladder 3	04/06/2025	Ok	Na	Na	Nigel Kelly Plumbing & Heating	