

GA3 - Report of Results of Inspections of: Work Equipment for Work at a Height



Name of person (or company) for whom the inspection was carried out: Kingscroft Development Ltd

Address where inspection was carried out (site or other workplace): Coill Clocha, Oranhill, Galway, H91 F9WH, Ireland (Oranmore)

Location & Description of Equipment & any Identification Numbers / Marks	Date and Time of Inspection	Results of Inspection* including defects & locations	Details of any corrective actions taken	Details of any further action necessary	Name and position of person making inspection	Signature of person who made inspection
Ladder 1	25/03/2026	Hood	N	N	David Holey	<i>David Holey</i>
Ladder 2	25/03/2026	Good	N	N	David Holey	<i>David Holey</i>