

GA3 - Report of Results of Inspections of: Work Equipment for Work at a Height



Name of person (or company) for whom the inspection was carried out:

Kingscroft Development Ltd

Address where inspection was carried out (site or other workplace):

Citywest Avenue, stop 4930, Brownsbarn, Dublin, Co. Dublin, Ireland
(Citywest)

Location & Description of Equipment & any Identification Numbers / Marks	Date and Time of Inspection	Results of Inspection* including defects & locations	Details of any corrective actions taken	Details of any further action necessary	Name and position of person making inspection	Signature of person who made inspection
Slings 6 m five ton	01/04/2026	All okay	Non-taken	Keeping daily checks	Dennis Thomas	