

GA3 - Report of Results of Inspections of: Work Equipment for Work at a Height



Name of person (or company) for whom the inspection was carried out:

Kingscroft Development Ltd

Address where inspection was carried out (site or other workplace):

Citywest Avenue, stop 4930, Brownsbarn, Dublin, Co. Dublin, Ireland
(Citywest)

Location & Description of Equipment & any Identification Numbers / Marks	Date and Time of Inspection	Results of Inspection* including defects & locations	Details of any corrective actions taken	Details of any further action necessary	Name and position of person making inspection	Signature of person who made inspection
Sling two meter three ton 220 0255	02/04/2026	Damaged sling	Sling out of service	Large tear out of service	Dennis Thomas	