

GA3 - Report of Results of Inspections of: Work Equipment for Work at a Height

Name of person (or company) for whom the inspection was carried out:

Kingscroft Development Ltd

Address where inspection was carried out (site or other workplace):

KILCARN WOOD 2 , Kilcarn, Navan, Co. Meath, C15D2E7 , Ireland
(Kilcarn)

Location & Description of Equipment & any Identification Numbers / Marks	Date and Time of Inspection	Results of Inspection* including defects & locations	Details of any corrective actions taken	Details of any further action necessary	Name and position of person making inspection	Signature of person who made inspection
2 step ladders	28/04/2026	Excellent	None	None	John Tormey - Concept Colours	