

# GA3 - Report of Results of Inspections of: Work Equipment for Work at a Height



Name of person (or company) for whom the inspection was carried out:

Kingscroft Development Ltd

Address where inspection was carried out (site or other workplace):

Coill Clocha, Oranhill, Galway, H91 F9WH, Ireland (Oranmore)

| Location<br>& Description of<br>Equipment & any<br>Identification<br>Numbers / Marks | Date and<br>Time of<br>Inspection | Results of Inspection*<br>including defects<br>& locations | Details of any corrective<br>actions taken | Details of any further<br>action necessary | Name and<br>position of<br>person<br>making<br>inspection | Signature of<br>person who<br>made<br>inspection |
|--------------------------------------------------------------------------------------|-----------------------------------|------------------------------------------------------------|--------------------------------------------|--------------------------------------------|-----------------------------------------------------------|--------------------------------------------------|
| Ladder 1 and 2                                                                       | 29/06/2026                        | Goox                                                       | N                                          | N                                          | David Holey                                               |                                                  |