

GA3 - Report of Results of Inspections of: Work Equipment for Work at a Height



Name of person (or company) for whom the inspection was carried out:

Kingscroft Development Ltd

Address where inspection was carried out (site or other workplace):

Castlelea Avenue, Cooltederry, Lansdowne, Co. Laois, R32 YPK3, Ireland (Portarlinton)

Location & Description of Equipment & any Identification Numbers / Marks	Date and Time of Inspection	Results of Inspection* including defects & locations	Details of any corrective actions taken	Details of any further action necessary	Name and position of person making inspection	Signature of person who made inspection
2nr a frame metal ladders	30/06/2025	Plot 12 Good condition	None	None	Colm O'Brien	