

# GA3 - Report of Results of Inspections of: Work Equipment for Work at a Height



Name of person (or company) for whom the inspection was carried out:

Kingscroft Development Ltd

Address where inspection was carried out (site or other workplace):

Citywest Avenue, stop 4930, Brownsbarn, Dublin, Co. Dublin, Ireland  
(Citywest)

| Location<br>& Description of<br>Equipment & any<br>Identification<br>Numbers / Marks | Date and<br>Time of<br>Inspection | Results of Inspection*<br>including defects<br>& locations | Details of any corrective<br>actions taken | Details of any further<br>action necessary | Name and<br>position of<br>person<br>making<br>inspection | Signature of<br>person who<br>made<br>inspection |
|--------------------------------------------------------------------------------------|-----------------------------------|------------------------------------------------------------|--------------------------------------------|--------------------------------------------|-----------------------------------------------------------|--------------------------------------------------|
| Ladder                                                                               | 30/06/2025                        | No defects                                                 | Na                                         | Na                                         | Declan<br>Lawless - Jol<br>Electrical                     |                                                  |