

Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	John Moore	Signature:	
Site Address:	Coill Clocha, Oranhill, Galway, H91 F9WH, Ireland	Location / Description of Scaffold:	House 174 to 175
Date & Time of Inspection:	2025-05-07 12:18:36		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Good	None
Sole Boards	Good	None
Base plates & Base Jacks	Good	None
Standards	Good	None
Ledgers	Good	None
Transoms	Good	None
Tie Spacing & Capacity	N/a	N/a
Anchorage test results	N/a	N/a
Facade bracing	Good	N/a
Pian bracing	N/a	N/a
Cross bracing	N/a	N/a
Guard rails	Good	None
Toe Boards	Good	None
Decking / scaffold boards	Good	N/a
Scaffolding signs and tags	Good	N/a
Loading in line with design / Manufacturer's instructions	Good	None
Access / egress	Good	N/a
User behaviour / housekeeping	Good	None

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Unauthorised alterations	N/a	N/a
Anticipated hazards (next 7 days)	N/a	N/a
Other (traffic, public, electricity)	N/a	N/a

Other outcomes of inspection / Observation: All good