


Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	Denis	Signature:	
Site Address:	Citywest Avenue, stop 4930, Brownsbarn, Dublin, Co. Dublin, Ireland	Location / Description of Scaffold:	Erect scaffold back 31 to 40 for roofers brickies plasterers
Date & Time of Inspection:	2025-05-27 07:47:08		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	None	Toe boards
Sole Boards	Good	None
Base plates & Base Jacks	Good	Good
Standards	Good	None
Ledgers	Good	None
Transoms	Good	None
Tie Spacing & Capacity	N a	None
Anchorage test results	N a	None
Facade bracing	N a	None
Pian bracing	N a	None
Cross bracing	Good	None
Guard rails	N a	None
Toe Boards	Good	Few toe boards
Decking / scaffold boards	Good	None
Scaffolding signs and tags	Good	Need sign
Loading in line with design / Manufacturer's instructions	Good	None
Access / egress	Good	None

Item Inspected	Condition (Include any defected found)	Corrections taken / required
User behaviour / housekeeping	Good	We had take blocks of birdcages
Unauthorised alterations	Good	None
Anticipated hazards (next 7 days)	All good	None
Other (traffic, public, electriaty)	Good	None

Other outcomes of inspection / Observation: All good